



report date: 2024-03-28

General information

Make	MINI
Model	COOPER S
Colour	Grey
Year of manufacture	2005
Top speed	137 mph
0 - 60 mph	7.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	220 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.4 mpg
CO2 emission	216 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-05-26
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-10
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	36
Total items failed	10

MOT #21	2024-01-11 10:44
MOT test number	885033698778
Result	✓ Passed
Next expiry date	2025-01-10
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #20	2024-01-11 10:44
MOT test number	469216484095
Result	✗ Failed
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #19** 2023-01-10 16:59**MOT test number** 207713065582**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Side repeater slightly discoloured (4.4.3 (a))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #18** 2022-01-06 08:03**MOT test number** 336709052791**Result** ✓ Passed**Advice** Oil leak but not excessive.**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #17** 2020-10-04 14:36**MOT test number** 856775693435**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #16**

2020-10-04 10:37

MOT test number

729850717752

Result**✗ Failed**

- MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Windscreen washer not working (3.5 (a))
- Advice** Offside Rear Nail in tyre
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15

2019-04-23 08:17

MOT test number

223676513243

Result**✓ Passed**

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14

2018-04-20 12:56

MOT test number

264103770929

Result**✓ Passed**

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Outer Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #13** 2018-04-20 11:05**MOT test number** 247963318430**Result** ✗ Failed**Fail** Fuel cap/sealing device sealing washer deteriorated (7.2.4c)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Outer Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)**MOT #12** 2017-06-15 15:19**MOT test number** 761333696042**Result** ✓ Passed**Advice** Offside Front inner edge worn low**MOT #11** 2017-06-08 14:54**MOT test number** 108111926908**Result** ✗ Failed**Advice** Offside Front inner edge worn low**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #10** 2016-05-12 14:11**MOT test number** 496187664104**Result** ✓ Passed**MOT #9** 2015-04-15 09:00**MOT test number** 298255605181**Result** ✓ Passed**Notice** Offside rear tyre inner edge wearing low

**MOT #8** 2014-03-06 13:13**MOT test number** 159125864434**Result** ✓ Passed**MOT #7** 2014-03-06 12:00**MOT test number** 458245364018**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Notice** Offside rear tyre flat (run flat, warning lamp not on)**MOT #6** 2013-03-21 15:07**MOT test number** 116630983489**Result** ✓ Passed**MOT #5** 2012-02-20 12:51**MOT test number** 427451552010**Result** ✓ Passed**MOT #4** 2011-03-07 11:41**MOT test number** 818316461033**Result** ✓ Passed



MOT #3	2011-03-04 15:47
MOT test number	578163161066
Result	✗ Failed
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
Fail	Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)

MOT #2	2010-02-13 10:17
MOT test number	562564640035
Result	✓ Passed

MOT #1	2009-02-23 15:42
MOT test number	133254959009
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
10 January 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	10 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-03-18
Last registration	2024-01-11
Complete history	See info



Registration #1	2005-03-18	26 mi
Registration #2	2009-02-23	17.443 mi
Registration #3	2010-02-13	18.930 mi
Registration #4	2011-03-04	20.772 mi
Registration #5	2011-03-07	20.772 mi
Registration #6	2012-02-20	20.654 mi
Registration #7	2013-03-21	21.047 mi
Registration #8	2014-03-06	21.585 mi
Registration #9	2014-03-06	21.585 mi
Registration #10	2015-04-15	23.001 mi
Registration #11	2016-05-12	23.186 mi
Registration #12	2017-06-08	24.166 mi
Registration #13	2018-06-20	25.277 mi
Registration #14	2019-06-20	26.277 mi
Registration #15	2020-06-20	27.277 mi
Registration #16	2021-06-20	28.277 mi
Registration #17	2022-06-20	29.277 mi
Registration #18	2023-06-20	30.277 mi
Registration #19	2024-01-11	31.277 mi
Registration #20	2024-01-11	32.277 mi
Registration #21	2024-01-11	33.277 mi
Registration #22	2024-01-11	34.277 mi
Registration #23	2024-01-11	35.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1925 mm
Height	1416 mm
Length	3655 mm
Wheel base	2467 mm
Kerb weight	1215 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Engine number	D062S341