



General information

Make	SUZUKI
Model	SX4 SZ4
Colour	Grey
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-12
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	36
Total items failed	15

MOT #19	2024-02-13 17:26
MOT test number	661602831429
Result	✓ Passed
Next expiry date	2025-02-12

MOT #18	2023-04-18 15:45
MOT test number	352891971784
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #17	2023-04-18 11:37
MOT test number	567204512853
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #16**

2022-04-22 07:37

MOT test number

700390285884

Result

✓ Passed

Advice Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #15**

2022-04-21 08:54

MOT test number

820922729098

Result

✗ Failed

Advice Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**MOT #14**

2021-04-23 15:14

MOT test number

174125007496

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2021-04-22 13:58

MOT test number

467787867859

Result**✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #12

2020-02-20 16:12

MOT test number

565853941536

Result**✓ Passed**

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #11

2020-02-20 14:30

MOT test number

949825193316

Result**✗ Failed**

- Fail** Nearside Rear Brake pipe excessively corroded axle pipe (1.1.11 (c))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Brake pipe excessively corroded axle pipe (1.1.11 (c))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #10**

2019-02-09 12:18

MOT test number

528360098201

Result

✓ Passed

Advice

Front number plate cracked.

Advice

Oil misting developed on nearside and offside rear shockers

Advice

Offside and nearside front suspension bottom arms rear bushes bonding weak

MOT #9

2019-02-09 10:00

MOT test number

950194215358

Result

✗ Failed

Advice

Offside and nearside front suspension bottom arms rear bushes bonding weak

Advice

Front number plate cracked.

Fail

Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Oil misting developed on nearside and offside rear shockers

Advice

Nearside front tyre badly scrubbed off at edges recommend new tyre

MOT #8

2018-02-21 16:40

MOT test number

576461237896

Result

✓ Passed

MOT #7

2017-06-20 13:46

MOT test number

231318665869

Result

✓ Passed

Advice

Oil misting on both rear shockers

Advice

Surface corrosion on offside front brake pipes.

**MOT #6** 2017-06-20 12:26**MOT test number** 402251655077**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Advice** Oil misting on both rear shockers**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively torn (8.2.2)**Advice** Surface corrosion on offside front brake pipes.**MOT #5** 2016-07-01 10:08**MOT test number** 921714818311**Result** ✓ Passed**Advice** Slight oil misting on both rear shock absorbers.**MOT #4** 2015-06-16 13:50**MOT test number** 309877365163**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #3** 2015-06-16 13:50**MOT test number** 426017365156**Result** ✗ Failed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)



MOT #2	2014-07-10 13:41
MOT test number	378721594109
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2013-07-09 10:25
MOT test number	426660493121
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
12 February 2025

Tax status	Valid until 1 May
Days left	2
MOT expiry date	12 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-08-13
Last registration	2024-02-13
Complete history	See info



Registration #1	2010-08-13	8 mi
Registration #2	2013-07-09	19.589 mi
Registration #3	2014-07-10	26.343 mi
Registration #4	2015-06-16	29.420 mi
Registration #5	2016-07-01	31.719 mi
Registration #6	2017-06-20	37.520 mi
Registration #7	2017-06-20	37.520 mi
Registration #8	2018-02-21	41.895 mi
Registration #9	2019-02-09	52.184 mi
Registration #10	2019-02-09	52.184 mi
Registration #11	2019-02-09	52.184 mi
Registration #12	2019-02-09	52.184 mi
Registration #13	2019-02-09	52.184 mi
Registration #14	2019-02-09	52.184 mi
Registration #15	2019-02-09	52.184 mi
Registration #16	2019-02-09	52.184 mi
Registration #17	2019-02-09	52.184 mi
Registration #18	2019-02-09	52.184 mi
Registration #19	2019-02-09	52.184 mi
Registration #20	2019-02-09	52.184 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1605 mm
Length	4255 mm
Wheel base	2500 mm
Kerb weight	1140 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1490340