





report date: 2024-03-29

#### General information

Make	FORD
Model	MONDEO EDGE
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	110 BHP
Max. torque	160 Nm at 4.100 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.2 mpg
CO2 emission	170 g/km
CO2 label	Н



CarCheck.co.uk page 1/15



report date: 2024-03-29

# Internet history

#### Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/15



SG10FKV report date: 2024-03-29

MOT history

MOT expiry date	2025-03-26
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	60
Total items failed	3

MOT #17	2024-03-22 08:54
MOT test number	500899648838
Result	<b>√</b> Passed
Next expiry date	2025-03-26
Advice Rear heat shield loose	

MOT #16	2023-03-27 11:00
MOT test	number 467627038216
Result	✓ Passed
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Rear exhaust heat shield loose

MOT #15		2023-03-27 10:14
MOT test	number	648026708319
Result		<b>×</b> Failed
MAJOR	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice	Rear exhaust heat shield loose	
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2	2.3 (d) (i))

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #14	2022-03-21 09:10
MOT test number	101071067342
Result	<b>✓</b> Passed
MOT #13	2021-02-10 12:11
MOT test number	904180140629
Result	<b>✓</b> Passed

MOT #12		2020-09-09 13:07
MOT test r	number	983784837427
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in excess	ive movement (5.3.4
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessiv	e movement (5.3.4 (a)
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both sic	de (1.1.14 (a) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 4/15



**DANGEROUS** 

**Advice** 

SG10FKV

report date: 2024-03-29

**MOT #11** 2020-09-08 13:11 **MOT** test number 458980091330 Result **X** Failed **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i)) **DANGEROUS** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10		2019-07-25 11:09
MOT test	number	199789020050
Result		<b>✓</b> Passed
Advice	Front Inner Brake pad(s) wearing thin both side (1.1.13 (a) (ii))	
Advice (i))	Offside Rear Suspension arm pin or bush worn but not resulting in excessive	movement (5.3.4 (a)
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both side	e (1.1.14 (a) (ii))
Advice (a) (i))		
Advice	Rear Inner Brake pad(s) wearing thin both side (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both side	e (1.1.14 (a) (ii))

CarCheck.co.uk page 5/15



report date: 2024-03-29

2018-07-26 10:15 MOT #9 667017480867 **MOT** test number ✓ Passed Result **Advice** Rear Brake pad(s) wearing thin both side (1.1.13 (a) (ii)) **Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii)) **Advice** Front Inner Brake pad(s) wearing thin both side (1.1.13 (a) (ii)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii)) **Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8		2018-07-26 07:55
MOT test	number	165664458216
Result		<b>★</b> Failed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both si	de (1.1.14 (a) (ii))
MAJOR	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
DANGER	<b>OUS</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.	3 (e))
Advice (i))	Offside Rear Suspension arm pin or bush worn but not resulting in excessive	re movement (5.3.4 (a)
Advice	Rear Brake pad(s) wearing thin both side (1.1.13 (a) (ii))	
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (	ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both sid	de (1.1.14 (a) (ii))
Advice (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in excess	sive movement (5.3.4
MAJOR	Rear Exhaust system insecure (6.1.2 (a))	
Advice	Front Inner Brake pad(s) wearing thin both side (1.1.13 (a) (ii))	

CarCheck.co.uk page 6/15



SG10FKV report date: 2024-03-29

MOT #7 2017-07-31 14:43

**MOT test number** 566879723489

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2016-07-28 10:10

**MOT test number** 937362543208

**Result** ✓ Passed

**MOT #5** 2015-07-31 09:03

**MOT test number** 358192515469

**Result** 
✓ Passed

**MOT #4** 2015-07-31 09:03

**MOT test number** 316052115439

Result × Failed

**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

MOT #3 2014-07-21 16:20

**MOT test number** 999222804205

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #2 2014-07-21 10:01

**MOT test number** 349932404231

**Result** X Failed

**Fail** Bonnet retaining device excessively deteriorated (8.4.2)

Fail An item not tested (Manual)

**MOT #1** 2013-08-01 10:40

**MOT test number** 807093213236

Result 

Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 8/15



report date: 2024-03-29

# Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	26 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	
HARMAN CONTRACTOR CONT	
************	
***************************************	
***************************************	
	More info >
Plate changes	
Coo in this shook if this FORD had different number plates	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	OK NEW
Plate since	
Current registration	UK SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



SG10FKV report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-10
Last registration	2024-03-22
Complete history	See info



Registration #1	2010-03-10	7 mi
Registration #2	2013-08-01	43.930 mi
Registration #3	2014-07-21	64.176 mi
Registration #4	2014-07-21	64.177 mi
Registration #5	2015-07-31	72.385 mi
Registration #6	2016-07-28	76.225 mi
Registration #7	2017-07-31	80.957 mi
Registration #8	2018-07-26	83.301 mi
Registration #9	2018-07-26	83.306 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1435 kg
Max. allowed weight	2050 kg

# Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles Carcheck.co.uk	2 page 15/15