





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	CLS CLS250 CDI BLUEEFFICIENCY SPOR
Colour	Blue
Year of manufacture	2013
Top speed	150 mph
0 - 100 km/h	8.4 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	125 kW / 170 HP / 204 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/11



✓ Passed

MOT history	
-------------	--

Result

MOT expiry date	2024-12-15
MOT pass rate	100 %
MOT passed	9
Failed MOT tests	0
Total advice items	8
Total items failed	0
MOT #9	2023-12-04 17:31
MOT test number	985096387797
Result	✓ Passed
Next expiry date	2024-12-15
MOT #8	2022-12-16 14:58
	2022 12 10 14.30

MOT #7	2021-11-25 14:42
MOT test number	908664413715
Result	✓ Passed

MOT #6	2020-12-03 13:16
MOT test number	932147331241
Result	✓ Passed

CarCheck.co.uk page 3/11



Advice

163NPN report date: 2024-03-28

MOT #5 2019-08-23 08:29 851316432209 **MOT** test number ✓ Passed Result **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** O/s/r inner brake pad worn close to wear indicator

MOT #4 2018-08-17 08:41 **MOT** test number 282348290543 Result ✓ Passed **MOT** #3 2017-08-24 08:34 889912422764 **MOT** test number

Result ✓ Passed **Advice** Offside Rear Tyre worn close to the legal limit 2.2mm (4.1.E.1) **Advice** Nearside Front Inner Brake pad(s) wearing thin (3.5.1g)

MOT #2 2016-10-25 16:02 **MOT** test number 479431030397 Result Passed

MOT #1 2016-08-24 13:05 585645059328 **MOT** test number Result ✓ Passed

Advice Nearside Front tyre wearing on inside indicating casing problem Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

CarCheck.co.uk page 4/11





Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	15 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MERCEDES-BENZ salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



More info >

Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report <u>here</u> .	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK NE
Plate since	

CarCheck.co.uk page 8/11



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-09-12
Last registration	2023-12-04
Complete history	See info



Registration #1	2013-09-12	21 mi
Registration #2	2016-08-24	25.236 mi
Registration #3	2016-10-25	25.982 mi
Registration #4	2017-08-24	40.990 mi
Registration #5	2018-08-17	68.758 mi
Registration #6	2019-08-23	96.686 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		0.074
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1881 mm
Height	1416 mm
Length	4940 mm
Wheel base	2874 mm
Kerb weight	1635 kg

Additional information

Fuel tank capacity	59 I
Number of axles	2
Engine number	65192431164317

CarCheck.co.uk page 11/11