



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Grey
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-07-09
Pictures	2
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-19
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-12
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	20
Total items failed	0

MOT #11	2023-09-05 15:14
MOT test number	965100114506
Result	✓ Passed
Next expiry date	2024-09-12
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Covers fitted
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #10	2023-09-05 11:47
MOT test number	164397978644
Result	✗ Failed
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
DANGEROUS	Offside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
DANGEROUS	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Covers fitted

**MOT #9** 2022-09-06 07:46**MOT test number** 293294309867**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #8** 2021-09-13 12:26**MOT test number** 820948764181**Result** ✓ Passed**MOT #7** 2021-05-05 08:34**MOT test number** 190826275789**Result** ✓ Passed**MOT #6** 2020-05-12 10:32**MOT test number** 132777735866**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing Both rear outer edges (5.2.3 (d) (ii))**Advice** Front Tyre slightly damaged/cracking or perishing Both front outer edges (5.2.3 (d) (ii))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**MOT #5** 2019-05-14 08:31**MOT test number** 917478189949**Result** ✓ Passed**Advice** Front Tyre slightly damaged/cracking or perishing offside and nearside (5.2.3 (d) (ii))**Advice** Rear Tyre slightly damaged/cracking or perishing offside and nearside (5.2.3 (d) (ii))



MOT #4	2018-05-02 07:38
MOT test number	486498820049
Result	✓ Passed
MOT #3	2017-05-18 08:45
MOT test number	368815845231
Result	✓ Passed
MOT #2	2016-07-19 10:17
MOT test number	465530197042
Result	✓ Passed
MOT #1	2015-08-03 12:50
MOT test number	277975015216
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
12 September 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	12 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-10-02
Last registration	2023-09-05
Complete history	See info



Registration #1	2012-10-02	27 mi
Registration #2	2015-08-03	5.135 mi
Registration #3	2016-07-19	6.376 mi
Registration #4	2017-05-18	7.216 mi
Registration #5	2018-05-02	10.156 mi
Registration #6	2019-05-14	13.925 mi
Registration #7	2020-05-12	15.794 mi
Registration #8	2021-05-12	27.000 mi
Registration #9	2022-05-12	27.000 mi
Registration #10	2023-05-12	27.000 mi
Registration #11	2024-05-12	27.000 mi
Registration #12	2025-05-12	27.000 mi
Registration #13	2026-05-12	27.000 mi
Registration #14	2027-05-12	27.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1097033