






report date: 2024-03-28

General information

| Make | FIAT |
|---------------------|----------------------|
| Model | FIORINO 16V MULTIJET |
| Colour | Red |
| Year of manufacture | 2011 |
| Top speed | 97 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 75 BHP |
|-------------------------|---------------------|
| Max. torque | 190 Nm at 1.500 rpm |
| Engine capacity | 1.248 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 62.8 mpg |



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-05-24

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-06-29 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 10 |
| Failed MOT tests | 5 |
| Total advice items | 5 |
| Total items failed | 12 |

| MOT #15 | 2023-06-20 14:55 |
|--|------------------|
| MOT test number | 163391007639 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-29 |
| Advice Rear Coil spring corroded (5.3.1 (b) (i)) | |

| MOT #14 | 2023-06-19 13:58 |
|--|------------------|
| MOT test number | 631488501701 |
| Result | X Failed |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Rear Coil spring corroded (5.3.1 (b) (i)) | |

| MOT #13 | 2022-06-30 12:05 |
|-----------------|------------------|
| MOT test number | 866639869337 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



report date: 2024-03-28

| MOT #12 | 2022-06-30 07:56 |
|--|------------------|
| MOT test number | 881642704347 |
| Result | × Failed |
| Fail Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Advice Nearside Rear Nail in tyre | |

| MOT #11 | 2021-11-17 12:52 |
|--|------------------|
| MOT test number | 462862159290 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #10 | 2020-11-11 16:25 |
|-----------------|------------------|
| MOT test number | 184847469601 |
| Result | ✓ Passed |
| | |
| MOT #9 | 2019-11-11 10:56 |
| MOT test number | 240029450600 |
| Result | ✓ Passed |
| | |
| MOT #8 | 2018-07-29 12:34 |
| MOT test number | 487875862344 |
| Result | ✓ Passed |
| | |

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #7 2018-07-20 15:08

MOT test number 206514784870

Result × Failed

Fail Nearside Rear Upper Suspension component pin or bush excessively worn shock (5.3.4 (a) (i))

Fail Nearside Front Service brake excessively fluctuating (1.2.1 (e))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Rear Upper Suspension component pin or bush excessively worn shock (5.3.4 (a) (i))

MOT #6 2017-06-26 07:05

MOT test number 304517027887

Result
✓ Passed

MOT #5 2017-06-26 07:05

MOT test number 359924532642

Result X Failed

Pass with rectification Nearside Headlamp aim too high (1.8)

MOT #4 2016-06-28 10:37

MOT test number 101337151277

Result

Passed

MOT #3 2015-05-20 15:35

MOT test number 206280645191

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT test number

709219735188

Result

Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Front coil spring broken (2.4.C.1a)



CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



PO11HVE report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

| \sim | | histo | |
|--------|------|-------|-----|
| ()\/ | vnor | nicto | rv/ |
| | | | |

| , | | |
|---|-----------|----|
| For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report | | e? |
| *************************************** | | |
| *************************************** | | |
| *************************************** | | |
| | | |
| *************************************** | | |
| *************************************** | | |
| | | |
| | More info | > |
| Plate changes | | |
| See in this check if this FIAT had different number plates. | | |
| Number of plates | | |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | NK SIE | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 9/12



PO11HVE report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2011-04-28 |
| Last registration | 2023-06-20 |
| Complete history | See info |



| Registration #1 | 2011-04-28 | 15 mi |
|------------------|------------|-----------|
| Registration #2 | 2014-05-01 | 49.549 mi |
| Registration #3 | 2015-05-19 | 69.151 mi |
| Registration #4 | 2015-05-20 | 69.151 mi |
| Registration #5 | 2016-06-28 | 90.870 mi |
| Registration #6 | 2017-06-26 | 93.413 mi |
| Registration #7 | 2017-06-26 | 93.413 mi |
| Registration #8 | 2018-07-20 | 96.849 mi |
| Registration #9 | 2018-07-29 | 96.849 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 44 |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | D.777 es |
| Registration #17 | | |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Additional information

| Fuel tank capacity | 45 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 2 |
| Engine number | 3798601 |

CarCheck.co.uk page 12/12