





### General information

Make	HYUNDAI
Model	I30 CRDI SE BLUE DRIVE
Colour	Black
Year of manufacture	2015
Top speed	117 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	83.1 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	А








# Internet history

Entry 1	
Date	2021-06-05
Pictures	15
Listing price	View report









source: autotrader.co.uk



### MOT history

MOT expiry date	2024-06-08
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	13
Total items failed	2

MOT #9	2023-06-05 07:49
MOT test number	572483961122
Result	✓ Passed
Next expiry date	2024-06-08

MOT #8	2022-05-19 15:16
MOT test number	111538600423
Result	✓ Passed

MOT #7	2022-05-19 08:14	
MOT test number	822128547090	
Result	🗙 Failed	
<b>MAJOR</b> Parking brake efficiency below requirements (1.4.2 (a) (i))		
<b>DANGEROUS</b> Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))		
Advice Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))		
<b>Pass with rectification</b> Offside Front Headlamp not working on dipped beam (4.1.1 (	a) (ii))	
<b>DANGEROUS</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e	:))	





MOT #6		2021-05-20 15:34
MOT test	number	598955844229
Result		✓ Passed
Advice (a) (ii))	Rear Brake disc worn, pitted or scored, but not seriously weakened Co	prroded - Both sides (1.1.14

MOT #5		2021-05-20 08:17
MOT test i	number	146362494821
Result		× Failed
<ul> <li>MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))</li> <li>Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Corroded - Both sides (1.1.14)</li> </ul>		
(a) (ii)) <b>Pass wit</b>	h rectification	Jearside Headlamp not working on dipped beam PRS (4.1.1 (a) (ii))

MOT #4	2020-06-09 12:43
MOT test number	226994379801
Result	✓ Passed
AdviceNearside Rear Nail in tyreAdviceRear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #3		2020-06-05 09:24
MOT test	number	446271299750
Result		🗙 Failed
Advice	Nearside Rear Nail in tyre	
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	))

MOT #2	2019-05-02 08:00
MOT test number	665830933562
Result	✓ Passed





MOT #1	2018-05-07 10:54
MOT test number	240401369625
Result	✓ Passed
Advice Offside Front wiper blade torn, still clearing the screen effectively	



Tax & MOT check

<b>Tax due:</b> 1 June 2024	✓ Taxed	<b>Expires:</b> 8 June 2024	√ МОТ
Tax status			Valid until 1 June
Days left			33
MOT expiry date			8 June 2024
Full MOT history			<u>See MOT history</u>
Tax calculation			
Vehicle class		49	

Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	
**********	
NUMBER OF CONTRACTOR OF CONTRA	
******	
*********	
********	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Carrent registration Fals since	
Current registration Fals since Current registration	







#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-30
Last registration	2023-06-05
Complete history	<u>See info</u>



Registration #1	2015-05-30	14 mi
Registration #2	2018-05-07	28.746 mi
Registration #3	2019-05-02	39.617 mi
Registration #4	2020-06-05	43.261 mi
Registration #5	2020-06-09	43.272 mi
Registration #6	2021-05-20	44.304 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		





### Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight	
Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1429 kg
Max. allowed weight	1920 kg
Additional information	
Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	D4FBFZ007917