





General information

Make	FIAT
Model	500 C POP DUALOGIC
Colour	White
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	110 g/km
CO2 label	В







Internet history	
Entry 1	
Date	2021-12-01
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-15
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	25
Total items failed	2

MOT #13	2023-10-16 09:18
MOT test number	831500542978
Result	✓ Passed
Next expiry date	2024-10-15

MOT #12	2022-08-26 12:43
MOT test number	473620609843
Result	✓ Passed

MOT #11		2021-09-06 12:15
MOT test	number	599906956370
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #10		2020-09-08 14:57
MOT test	number	768271807150
Result		✓ Passed
Advice	Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor (i))		
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #9	2020-09-08 13:48
MOT test number	412337029229
Result	🗙 Failed
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light (i))	sources (4.7.1 (b)
Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #8	2019-08-16 07:37
MOT test number	492249928964
Result	✓ Passed
Advice Nearside Front Upper Macpherson strut pin or bush worn but not resul (5.3.4 (a) (i))	ting in excessive movement
Advice Items removed from driver's view prior to test	
Advice Offside Front Upper Macpherson strut pin or bush worn but not resultin (5.3.4 (a) (i))	ng in excessive movement





MOT #7		2018-07-26 13:04
MOT test number		763741117304
Result		✓ Passed
Advice Exhaust syst	em corroded	
МОТ #6		2017-08-02 10:34
MOT test number		287000740479
Result		✓ Passed
Advice Front brake of	discs worn to service limits	
Advice N/s/r tyre 2m	nm and worn on inner and outer edge	
Advice Corrosion to	rear exhaust box outer skin	

MOT #5 2017-08-02 10:34

Result		🗙 Failed
Advice Corrosion to rear exhaust box outer skin		
Advice Front brake disc	s worn to service limits	
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	
Advice N/s/r tyre 2mm	and worn on inner and outer edge	

MOT #4		2016-08-20 08:52
MOT test	number	598481515356
Result		✓ Passed
Advice	Nearside Front Macpherson strut has slight movement at the upper attachme	ent (2.5.A.1c)
Advice	Hi level brake light not working	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Inner sidewall tyre splitting	

977912366600





MOT #3	2015-08-25 11:24
MOT test number	738335386129
Result	✓ Passed
Advice Items removed from windscreen prior to test	
MOT #2	2014-08-22 09:56
MOT test number	175884334247
Result	✓ Passed
MOT #1	2013-08-23 14:48
MOT test number	709505633219
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 15 October 2024
Tax status	Valid until 1 October
Days left	154
MOT expiry date	15 October 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-07-29
Last registration	2023-10-16
Complete history	See info



Registration #1	2010-07-29	20 mi
Registration #2	2013-08-23	17.901 mi
Registration #3	2014-08-22	23.237 mi
Registration #4	2015-08-25	27.180 mi
Registration #5	2016-08-20	31.770 mi
Registration #6	2017-08-02	36.464 mi
Registration #7	2017-08-02	36.464 mi
Registration #8	2018-07-26	38.961 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 mi





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1340 kg
Additional information	
Fuel tank capacity	35
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles	2
Engine number	5877559