



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BORA S TDI (100BHP)
Colour	Silver
Year of manufacture	2005
Top speed	117 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	325 Nm at 1.800 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-12-13
Pictures	10
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2023-12-05
MOT pass rate	94 %
MOT passed	16
Failed MOT tests	1
Total advice items	15
Total items failed	5

MOT #17 2022-12-01 16:19

MOT test number 103160276291

Result ✓ Passed

Next expiry date 2023-12-05

**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Front Vehicles internal headlight adjuster altered to recheck lights

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2021-12-06 14:42

MOT test number 739700180030

Result ✓ Passed

MOT #15 2021-02-06 10:04

MOT test number 672729842427

Result ✓ Passed

**MOT #14** 2020-02-29 08:39**MOT test number** 195998001743**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #13** 2019-02-16 09:57**MOT test number** 592446657655**Result** ✓ Passed**MOT #12** 2018-02-23 11:31**MOT test number** 509258278529**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2017-02-18 09:00**MOT test number** 156947556848**Result** ✓ Passed**MOT #10** 2016-02-27 09:59**MOT test number** 858445829805**Result** ✓ Passed**MOT #9** 2015-02-03 16:59**MOT test number** 875514435080**Result** ✓ Passed



<b>MOT #8</b>	2014-02-22 12:27
<b>MOT test number</b>	408023854042
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake pad(s) wearing thin (3.5.1g)

<b>MOT #7</b>	2014-02-22 10:38
<b>MOT test number</b>	986883554042
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
<b>Fail</b>	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
<b>Advice</b>	Rear Brake pad(s) wearing thin (3.5.1g)
<b>Fail</b>	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
<b>Fail</b>	Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
<b>Fail</b>	Front brake disc in such a condition that it is seriously weakened (3.5.1i)

<b>MOT #6</b>	2013-03-16 12:21
<b>MOT test number</b>	697995273009
<b>Result</b>	✓ Passed

<b>MOT #5</b>	2012-02-25 14:17
<b>MOT test number</b>	758716952013
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2011-03-03 09:16
<b>MOT test number</b>	218332961083
<b>Result</b>	✓ Passed

**MOT #3** 2010-03-24 17:53**MOT test number** 612023080013**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2009-03-24 17:28**MOT test number** 494343389083**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2008-03-11 12:33**MOT test number** 850251378014**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✗  
**MOT**  
**Expired:**  
5 December 2023

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	217
<b>MOT expiry date</b>	5 December 2023
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>LT05WCC</b>
Plate since	2024-03-28
Current registration	<b>LT05WCC</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-03-11
Last registration	2022-12-01
Complete history	<a href="#">See info</a>



Registration #1	2005-03-11	11 mi
Registration #2	2008-03-11	38.107 mi
Registration #3	2009-03-24	50.706 mi
Registration #4	2010-03-24	61.975 mi
Registration #5	2011-03-03	72.956 mi
Registration #6	2012-02-25	84.874 mi
Registration #7	2013-03-16	98.009 mi
Registration #8	2014-02-22	109.819 mi
Registration #9	2014-02-22	109.819 mi
Registration #10	2015-02-03	121.793 mi
Registration #11	2015-05-20	131.377 mi
Registration #12	2015-05-20	131.377 mi
Registration #13	2015-05-20	131.377 mi
Registration #14	2015-05-20	131.377 mi
Registration #15	2015-05-20	131.377 mi
Registration #16	2015-05-20	131.377 mi
Registration #17	2015-05-20	131.377 mi
Registration #18	2015-05-20	131.377 mi
Registration #19	2015-05-20	131.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

ASZ546881