



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO S (79BHP)
Colour	Blue
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	152 g/km
CO2 label	G





MOT history

MOT expiry date	2020-09-02
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	9
Total items failed	21

MOT #17	2019-08-30 10:24
MOT test number	660419094115
Result	✓ Passed
Next expiry date	2020-09-02

MOT #16	2019-08-30 10:24
MOT test number	414894127035
Result	✗ Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #15	2018-09-03 15:46
MOT test number	873549820154
Result	✓ Passed
Advice	Rear Exhaust noisy (8.1.1 (a))

**MOT #14**

2018-09-03 08:11

MOT test number

635275170558

Result**✗ Failed**

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Rear Exhaust noisy (8.1.1 (a))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #13

2017-08-21 10:03

MOT test number

256808505553

Result**✓ Passed**

- Advice** Exhaust downpipe blowing around flexible section area

**MOT #12**

2017-08-18 09:13

MOT test number

427713736677

Result**✗ Failed**

- Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm bald on extreme inside edge (4.1.E.1)
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Exhaust downpipe blowing around flexible section area
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm bald on extreme inside edge (4.1.E.1)
- Pass with rectification** Nearside Front Headlamp aim too high (1.8)

MOT #11

2016-08-30 13:38

MOT test number

755325794940

Result**✓ Passed****MOT #10**

2015-04-02 09:13

MOT test number

386752395000

Result**✓ Passed****MOT #9**

2014-04-28 16:45

MOT test number

565698114122

Result**✓ Passed**

- Notice** Under-trays fitted obscuring some underside components
- Notice** Items removed from driver's view prior to test

**MOT #8** 2014-04-28 14:20**MOT test number** 907498214185**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Items removed from driver's view prior to test**MOT #7** 2013-04-09 16:17**MOT test number** 506349893038**Result** ✓ Passed**MOT #6** 2013-04-09 09:54**MOT test number** 415019693068**Result** ✗ Failed**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Notice** Both rear tyres perished**MOT #5** 2012-04-18 09:41**MOT test number** 315679902161**Result** ✓ Passed**MOT #4** 2012-04-17 10:33**MOT test number** 687228602131**Result** ✗ Failed**Fail** Offside Lower Rear position lamp(s) not working (1.1.A.3b)**Fail** Nearside front brake juddering severely (3.7.A.2b)



MOT #3	2011-03-25 17:19
MOT test number	498214381068
Result	✓ Passed

MOT #2	2011-03-25 10:47
MOT test number	589294281044
Result	✗ Failed
<div><div>Fail</div>Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)</div>	

MOT #1	2010-03-12 16:21
MOT test number	890171470056
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 November 2020

✕
MOT

Expired:
2 September 2020

Tax status	Expired at 1 November 2020
Days left	1276 days too late
MOT expiry date	2 September 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SV07MXW
Plate since	2024-03-29
Current registration	 SV07MXW
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-03-01
Last registration	2019-08-30
Complete history	See info



Registration #1	2007-03-01	20 mi
Registration #2	2010-03-12	15.354 mi
Registration #3	2011-03-25	26.938 mi
Registration #4	2011-03-25	26.938 mi
Registration #5	2012-04-17	38.038 mi
Registration #6	2012-04-18	38.038 mi
Registration #7	2013-04-09	45.584 mi
Registration #8	2013-04-09	45.584 mi
Registration #9	2014-04-28	53.625 mi
Registration #10	2019-08-30	55.557 mi
Registration #11	2019-08-30	55.557 mi
Registration #12	2019-08-30	55.557 mi
Registration #13	2019-08-30	55.557 mi
Registration #14	2019-08-30	55.557 mi
Registration #15	2019-08-30	55.557 mi
Registration #16	2019-08-30	55.557 mi
Registration #17	2019-08-30	55.557 mi
Registration #18	2019-08-30	55.557 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1191 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BUD 175163