



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO L1H1 2000 SPORTIVE CDTI
Colour	White
Year of manufacture	2018
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-08
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-03
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	13
Total items failed	4

MOT #6	2023-11-01 15:16
MOT test number	774666865333
Result	✓ Passed
Next expiry date	2024-11-03
Minor	Nearside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #5	2023-11-01 09:21
MOT test number	344677132177
Result	✗ Failed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Headlamp aim unable to be tested Due to headlamp not working. (4.1.2 (b))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Nearside Front Nail in tyre

**MOT #4**

2022-11-04 11:05

MOT test number

205818054407

Result

✓ Passed

Advice Coolant level close to minimum mark in reservoir**Advice** Offside Front Nail in tyre Nail within central / inner tread**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH front discs corroding slightly on shoulders (1.1.14 (a) (ii))**MOT #3**

2022-11-04 11:05

MOT test number

663346517535

Result

✗ Failed

Pass with rectification Offside Front Daytime running lamp not working (4.2.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH front discs corroding slightly on shoulders (1.1.14 (a) (ii))**Advice** Coolant level close to minimum mark in reservoir**Advice** Offside Front Nail in tyre Nail within central / inner tread**MOT #2**

2021-12-10 15:30

MOT test number

107231246541

Result

✓ Passed

Advice Rear Exhaust mounting defective (6.1.2 (a))**MOT #1**

2021-03-25 16:54

MOT test number

908946100948

Result

✓ Passed

Advice Offside Rear Nail in tyre**Minor** Nearside Outer Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Central Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
3 November 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	3 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-06-18
Last registration	2023-11-01
Complete history	See info



Registration #1	2018-06-18	9 mi
Registration #2	2021-03-25	83.620 mi
Registration #3		
Registration #4	2021-12-10	87.049 mi
Registration #5		
Registration #6		
Registration #7		
Registration #8		

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	91%
Children	81%
Pedestrian	58%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1290 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	330A10006534855 LN9