



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE SPORT TSI 140
Colour	Red
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	220 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	169 g/km
CO2 label	H






Internet history

Entry 2


Date	2021-09-02
Pictures	11
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-31
Pictures	11
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2023-01-13
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	13
Total items failed	8

MOT #16	2022-01-08 16:15
----------------	------------------

MOT test number	156188697829
------------------------	--------------

Result	✓ Passed
---------------	----------

Next expiry date	2023-01-13
-------------------------	------------

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Headlamp lens slightly defective Both nearside and offside front (4.1.1 (b) (i))

Advice Tyre worn close to legal limit/worn on edge Both nearside and offside front (5.2.3 (e))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15	2021-01-14 14:20
----------------	------------------

MOT test number	148492944599
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice Exhaust deteriorated

**MOT #14**

2021-01-08 14:49

MOT test number

433523035882

Result**✗ Failed**

- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced outer sill holed (6.1.1 (c) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Exhaust deteriorated
- Advice** Tyre worn close to legal limit/worn on edge both rear on limit 1.6mm (5.2.3 (e))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #13

2020-01-08 16:51

MOT test number

700549733738

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge borderline (5.2.3 (e))

MOT #12

2020-01-07 11:47

MOT test number

668730462532

Result**✗ Failed**

- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge borderline (5.2.3 (e))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Exhaust has a minor leak of exhaust gases middle silencer (6.1.2 (a))



MOT #11	2019-03-04 17:37
MOT test number	282634756371
Result	✓ Passed
MOT #10	2018-09-25 12:51
MOT test number	810624578258
Result	✓ Passed
MOT #9	2017-09-11 10:23
MOT test number	919727493038
Result	✓ Passed
MOT #8	2016-09-14 13:57
MOT test number	643410536138
Result	✓ Passed
MOT #7	2015-09-28 10:55
MOT test number	187852285150
Result	✓ Passed
MOT #6	2014-09-23 10:45
MOT test number	745656164273
Result	✓ Passed
MOT #5	2013-09-26 09:48
MOT test number	965749063243
Result	✓ Passed
MOT #4	2012-09-08 08:57
MOT test number	637932852241
Result	✓ Passed



MOT #3	2011-09-17 09:59
MOT test number	458250461285
Result	✓ Passed
MOT #2	2010-09-11 12:11
MOT test number	220854350234
Result	✓ Passed
MOT #1	2010-09-11 11:28
MOT test number	142854550268
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✕
Untaxed

Tax expired:
1 September 2022

✕
MOT

Expired:
13 January 2023

Tax status	Expired at 1 September
Days left	605 days too late
MOT expiry date	13 January 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 RK57YYN
Plate since	2024-03-28
Current registration	 RK57YYN
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-28
Last registration	2022-01-08
Complete history	See info



Registration #1	2007-09-28	21 mi
Registration #2	2010-09-11	32.567 mi
Registration #3	2010-09-11	32.567 mi
Registration #4	2011-09-17	49.159 mi
Registration #5	2012-09-08	62.076 mi
Registration #6	2013-09-26	75.250 mi
Registration #7	2014-09-23	86.737 mi
Registration #8	2015-09-28	98.207 mi
Registration #9	2016-09-14	109.186 mi
Registration #10	2017-09-11	122.144 mi
Registration #11	2018-09-11	135.102 mi
Registration #12	2019-09-11	148.060 mi
Registration #13	2020-09-11	161.018 mi
Registration #14	2021-09-11	173.976 mi
Registration #15	2022-01-08	186.934 mi
Registration #16	2022-01-08	186.934 mi
Registration #17	2022-01-08	186.934 mi
Registration #18	2022-01-08	186.934 mi
Registration #19	2022-01-08	186.934 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1423 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BMY 023990