



report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | KIA            |
| Model               | SORENTO XS     |
| Colour              | Black          |
| Year of manufacture | -              |
| Top speed           | 113 mph        |
| 0 - 60 mph          | 11.6 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 168 BHP             |
| Max. torque             | 392 Nm at 2.000 rpm |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 28.3 mpg            |
| Consumption extra urban | 42.2 mpg            |
| Consumption combined    | 35.8 mpg            |



LABEL UNKNOWN



Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-02-01                  |
| Pictures      | 1                           |
| Listing price | <a href="#">View report</a> |



source: [autoonline.co.uk](#)

**MOT history**

|                         |   |
|-------------------------|---|
| <b>MOT #13</b>          | 2021-12-07 09:39  |
| <b>MOT test number</b>  | 935112507539  |
| <b>Result</b>           | ✓ Passed  |
| <b>Next expiry date</b> | 2022-12-06  |
| <b>Advice</b>           | Offside Rear Brake pipe corroded, covered in grease or other material slight corrosion (1.1.11 (c)) |
| <b>Advice</b>           | Offside Front Tyre worn close to legal limit/worn on edge worn on inside edge (5.2.3 (e))           |

|                        |  |
|------------------------|--|
| <b>MOT #12</b>         | 2020-12-02 09:22                                 |
| <b>MOT test number</b> | 454956330791                                     |
| <b>Result</b>          | ✓ Passed   |
| <b>Advice</b>          | Oil leak, but not excessive (8.4.1 (a) (i))      |
| <b>Advice</b>          | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

|                        |  |
|------------------------|--|
| <b>MOT #10</b>         | 2018-10-23 14:27   |
| <b>MOT test number</b> | 567353582240   |
| <b>Result</b>          | ✓ Passed   |
| <b>Advice</b>          | Oil leak, but not excessive (8.4.1 (a) (i))  |
| <b>Minor</b>           | Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) |

**MOT #9** 2018-10-19 08:25**MOT test number** 541857330013**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**Fail** Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #8** 2017-10-23 13:36**MOT test number** 218117246192**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2016-10-04 08:52**MOT test number** 669241686206**Result** ✓ Passed**Advice** Both rear tyres wearing close to limit on center section of tread.**MOT #6** 2015-10-12 10:50**MOT test number** 709252688696**Result** ✓ Passed**MOT #5** 2015-10-12 10:49**MOT test number** 309414309326**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)



|  |                  |
|--|------------------|
| <b>MOT #4</b>  | 2014-09-11 11:32 |
| <b>MOT test number</b>   | 539794954209     |
| <b>Result</b>  | ✓ Passed         |
| <div><b>Notice</b> Front tyres wearing on inner edges</div>  |                  |
| <b>MOT #3</b>  | 2013-09-20 12:55 |
| <b>MOT test number</b>   | 846343963295     |
| <b>Result</b>  | ✓ Passed         |
| <b>MOT #2</b>  | 2012-09-10 16:14 |
| <b>MOT test number</b>   | 317894752237     |
| <b>Result</b>  | ✓ Passed         |
| <b>MOT #1</b>  | 2012-09-05 17:31 |
| <b>MOT test number</b>   | 558719442250     |
| <b>Result</b>  | ✗ Failed         |
| <div><b>Fail</b> Centre Rear Seat belt damaged sufficient to obstruct correct operation of the belt (5.2.2a)</div> |                  |



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this KIA had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2024-03-29 |
| Current registration |            |
| Plate since          | 2024-03-29 |

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 15                       |
| First mileage registration | 2009-09-30               |
| Last registration          | 2021-12-07               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2009-09-30 | 29 mi      |
| Registration #2  | 2012-09-05 | 28.012 mi  |
| Registration #3  | 2012-09-10 | 28.012 mi  |
| Registration #4  | 2013-09-20 | 40.130 mi  |
| Registration #5  | 2014-09-11 | 53.379 mi  |
| Registration #6  | 2015-10-12 | 65.323 mi  |
| Registration #7  | 2015-10-12 | 65.323 mi  |
| Registration #8  | 2016-10-04 | 79.542 mi  |
| Registration #9  | 2017-09-20 | 93.761 mi  |
| Registration #10 | 2018-09-11 | 107.980 mi |
| Registration #11 | 2019-09-02 | 122.199 mi |
| Registration #12 | 2020-08-23 | 136.418 mi |
| Registration #13 | 2021-08-14 | 150.637 mi |
| Registration #14 | 2022-08-05 | 164.856 mi |
| Registration #15 | 2023-07-26 | 179.075 mi |

More info >



Car features

The KIA factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 87%                             |
| Children       | 84%                             |
| Pedestrian     | 44%                             |
| Safety systems | 71%                             |
| Overall rating | 76%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1885 mm |
| Height              | 1805 mm |
| Length              | 4590 mm |
| Wheel base          | 2710 mm |
| Kerb weight         | 2065 kg |
| Max. allowed weight | 2640 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 80 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |

|                        |             |
|------------------------|-------------|
| <b>Number of axles</b> | 2           |
| <b>Engine number</b>   | D4CB8349539 |