

Ford



### General information

Make	FORD
Model	KA ZETEC
Colour	Blue
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual
Colour Year of manufacture Top speed 0 - 60 mph	Blue 2009 99 mph 13.1 seconds

### Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С





# MOT history

MOT expiry date	2022-01-18
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	20
Total items failed	0

MOT #10	2021-01-19 13:21
MOT test number	848203362011
Result	✓ Passed
Next expiry date	2022-01-18

МОТ #9	2020-01-02 11:08
MOT test number	258700809018
Result	✓ Passed

MOT #8	2018-07-11 14:45
MOT test number	920084204902
Result	✓ Passed
Advice Coil springs corroded	
Advice Nearside Rear Tyre has flat spot	



AU59XRO
report date: 2024-03-29

MOT #7		2018-07-10 13:50
MOT test	number	621090688444
Result		🗙 Failed
MAJOR	Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))	
MAJOR	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Offside Rear Coil spring mounting corroded but not seriously weakened (	5.3.1 (b) (i))
MAJOR	Offside Front Tyre has a bulge, caused by separation or partial failure of i	ts structure (5.2.3 (d) (i))
Advice requires a	Rear Brakes imbalanced requirements only just met. It would appear that djustment or repair. (1.2.1 (b) (i))	t the braking system
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Exhaust system corroded	
Advice	Nearside Rear Coil spring mounting corroded but not seriously weakened	(5.3.1 (b) (i))

MOT #6		2017-07-17 11:59
MOT test	number	394782322288
Result		✓ Passed
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Rear exhaust deteriorated	
Advice	Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)	

MOT #5	2016-07-22 15:42
MOT test number	662380106004
Result	✓ Passed

MOT #4	2015-07-11 12:37
MOT test number	109542195185
Result	✓ Passed





MOT #3	2014-07-16 14:57
MOT test number	796017494166
Result	✓ Passed
Notice Rear silencer corroded	
Advice Nearside Front Road wheel with a slightly distorted bead rin	m (4.2.A.1a)
Notice Rear exhaust clamp missing	
MOT #2	2013-07-23 11:04
MOT test number	967394303282
Result	✓ Passed
MOT #1	2012-08-30 14:09
MOT test number	159553442226
Result	✓ Passed
Notice Rear box slighty rusty	
Advice Offside Front Road wheel with a slightly distorted bead rim	(4.2.A.1a)
<b>Notice</b> Items removed from driver's view prior to test	



AU59XRO report date: 2024-03-29

Tax & MOT check

X Untaxed Tax expired: 22 January 2021	<b>Expired:</b> 18 January 2022	Х МОТ
Tax status		Expired at 22 January 2021
Days left		1192 days too late
MOT expiry date		18 January 2022
Full MOT history		See MOT history
Tax calculation		
Vehicle class	48	

Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2009-09-01
Last registration	2021-01-19
Complete history	See info



Registration #1	2009-09-01	21 mi
Registration #2	2012-08-30	32.001 mi
Registration #3	2013-07-23	40.306 mi
Registration #4	2014-07-16	46.388 mi
Registration #5	2015-07-11	55.754 mi
Registration #6	2016-07-22	60.654 mi
Registration #7		11.777 mi
Registration #8		11.777 mil
Registration #9		11.777 est
Registration #10		11.777 est
Registration #11		11.227 est





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg
Additional information	
Fuel tank capacity	35
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles	2
Engine number	5187434