



WV07EHG

report date: 2024-03-29

General information

Make	FIAT
Model	SCUDO COMFORT SWB P/V 90 MULTIJET
Colour	White
Year of manufacture	2007
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-05-04
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	49
Total items failed	30

MOT #21 2023-05-05 17:02

MOT test number 529303317630

Result ✓ Passed

Next expiry date 2024-05-04

Advice Nearside Front Upper Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security turret (6.2.2 (d) (i))

Advice Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced jacking point (6.1.1 (c) (i))

Advice Offside Front Upper Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security turret (6.2.2 (d) (i))

MOT #20 2022-04-12 14:55

MOT test number 179387657052

Result ✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Rear surface corrosion rear axle assembly

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Central exhaust system surface corrosion

**MOT #19**

2020-11-11 16:52

MOT test number

323147312145

Result

✓ Passed

- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust heat shield not secure
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Suspension corroded

MOT #18

2019-11-12 11:59

MOT test number

654231462421

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Service brake requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))
- Advice** Rear All direction indicators slightly discoloured (4.4.3 (a))
- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Underbody corrosion
- Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #17**

2019-11-07 16:58

MOT test number

970302667927

Result**✗ Failed**

- Advice** Coolant level low
- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Advice** Underbody corrosion
- Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Power steering reservoir level low
- Advice** Service brake requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Rear All direction indicators slightly discoloured (4.4.3 (a))

MOT #16

2018-11-08 14:18

MOT test number

343943967187

Result**✓ Passed**

- Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #15**

2018-11-02 09:41

MOT test number

418136863277

Result

✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Obligatory mirror missing (3.3 (a))
- Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #14

2017-10-28 08:09

MOT test number

493894887831

Result

✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #13

2017-10-27 08:17

MOT test number

879481621358

Result

✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Rear Exhaust system not adequately supported (7.1.1)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #12

2016-10-25 15:17

MOT test number

306844443873

Result

✓ Passed

**MOT #11** 2016-10-25 08:12**MOT test number** 399642122073**Result** ✗ Failed

- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Offside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Centre Stop lamp not working (1.2.1b)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)

MOT #10 2015-10-27 12:31**MOT test number** 522025072292**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #9 2015-10-26 11:29**MOT test number** 228204805810**Result** ✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Rear Exhaust system not adequately supported (7.1.1)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)

**MOT #8** 2014-10-25 10:39**MOT test number** 789728094255**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #7** 2014-10-24 15:22**MOT test number** 327897194442**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Exhaust system not adequately supported (7.1.1)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #6** 2013-10-26 09:53**MOT test number** 165809793224**Result** ✓ Passed**MOT #5** 2012-10-31 13:38**MOT test number** 139905502372**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2012-10-31 10:35**MOT test number** 966095802337**Result** ✗ Failed

Fail Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Centre Stop lamp not working (1.2.1b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2011-10-13 09:47**MOT test number** 299296681295**Result** ✓ Passed**MOT #2** 2011-10-05 15:09**MOT test number** 249278571241**Result** ✗ Failed

Notice Nearside front disc scored

Fail Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)

MOT #1 2010-09-09 09:02**MOT test number** 554562150221**Result** ✓ Passed



Tax & MOT check

✗
Untaxed

Tax expired:
1 February 2024

✓
MOT

Expires:
4 May 2024

Tax status	Expired at 1 February 2024
Days left	88 days too late
MOT expiry date	4 May 2024
Full MOT history	See MOT history



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	WV07EHG
Plate since	2019-09-29
Current registration	WV07EHG
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	22
First mileage registration	2007-03-15
Last registration	2023-05-05
Complete history	See info



Registration #1	2007-03-15	25 mi
Registration #2	2010-09-09	52.569 mi
Registration #3	2011-10-05	61.504 mi
Registration #4	2011-10-13	61.504 mi
Registration #5	2012-10-31	69.544 mi
Registration #6	2012-10-31	69.544 mi
Registration #7	2013-10-26	78.876 mi
Registration #8	2014-10-24	86.895 mi
Registration #9	2014-10-25	86.895 mi
Registration #10	2015-10-26	151.990 mi
Registration #11	2015-10-27	151.990 mi
Registration #12	2016-10-27	151.990 mi
Registration #13	2016-10-27	151.990 mi
Registration #14	2016-10-27	151.990 mi
Registration #15	2016-10-27	151.990 mi
Registration #16	2016-10-27	151.990 mi
Registration #17	2016-10-27	151.990 mi
Registration #18	2016-10-27	151.990 mi
Registration #19	2016-10-27	151.990 mi
Registration #20	2016-10-27	151.990 mi
Registration #21	2016-10-27	151.990 mi
Registration #22	2016-10-27	151.990 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3
Engine number	0019447