



PX62ZPZ

report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO POP
Colour	White
Year of manufacture	2012
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	123 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-12-02
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-01-10
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	19
Total items failed	12

MOT #13 2023-01-11 11:06

MOT test number 764833834086

Result ✓ Passed

Next expiry date 2024-01-10

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2023-01-11 11:06

MOT test number 750644538794

Result ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #11** 2022-01-04 16:53**MOT test number** 351017237483**Result** ✓ Passed**MOT #10** 2021-02-17 14:21**MOT test number** 208541048376**Result** ✓ Passed**MOT #9** 2020-02-13 12:23**MOT test number** 311708146454**Result** ✓ Passed**MOT #8** 2019-02-19 16:49**MOT test number** 247063896201**Result** ✓ Passed**MOT #7** 2019-02-19 12:30**MOT test number** 216197749367**Result** ✗ Failed

DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #6 2018-02-19 11:04**MOT test number** 938535209679**Result** ✓ Passed

Advice Oil leak Gearbox

Advice Rear Exhaust rear silencer is slightly corroded

Advice Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2017-01-10 12:00**MOT test number** 703044192215**Result** ✓ Passed**MOT #4** 2017-01-09 12:47**MOT test number** 945471884710**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2016-09-29 16:00**MOT test number** 508091259236**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** N/s/f tyre has cut in outer sidewall.**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** N/s driveshaft seal leaking.**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Advice** O/s/r tyre is perished.**Fail** Horn not working (1.6.2a)**MOT #2** 2015-10-02 10:50**MOT test number** 322006490130**Result** ✓ Passed



MOT #1	2015-10-02 09:32
MOT test number	253063472943
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Rear Direction indicator has less than 50% of the light sources illuminating (1.4.A.2c)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-06-29
Current registration	 XXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-09-29
Last registration	2023-01-11
Complete history	See info



Registration #1	2012-09-29	16 mi
Registration #2	2015-10-02	25.280 mi
Registration #3	2015-10-02	25.280 mi
Registration #4	2016-09-29	35.269 mi
Registration #5	2017-01-09	35.371 mi
Registration #6	2017-01-10	37.372 mi
Registration #7	2018-02-19	42.132 mi
Registration #8	2019-02-19	48.326 mi
Registration #9	2019-05-29	55.377 mi
Registration #10	2019-05-29	55.377 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	1575 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	6875035