



HONDA



LB6IHXZ


report date: 2024-03-28

General information

Make	HONDA
Model	INSIGHT IMA EX
Colour	Brown
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	120 Nm at 4.500 rpm
Engine capacity	1.339 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	60.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	61.4 mpg
CO2 emission	105 g/km
CO2 label	B





**report date:** 2024-03-28

### Entry 1

# AA

## Warranty



Protection from electrical and mechanical faults.



12 months\* free Basic Breakdown Cover\* or an upgrade for Members.



Nationwide approved repair network.

\*Standard cover is 12 months/unlimited mileage breakdown assistance. Repairs to electrical and mechanical components are repaired for 12 months/unlimited mileage. Breakdown cover is provided for 12 months/unlimited mileage. Repairs to electrical and mechanical components are repaired for 12 months/unlimited mileage. Repairs to electrical and mechanical components are repaired for 12 months/unlimited mileage.



CarCheck.co.uk



## MOT history

MOT expiry date	2024-10-22
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	12
Total items failed	6

MOT #14	2023-10-23 06:44
MOT test number	302559375061
Result	✓ Passed
Next expiry date	2024-10-22
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #13	2022-10-20 06:26
MOT test number	133299770896
Result	✓ Passed

MOT #12	2021-10-19 11:45
MOT test number	273979535062
Result	✓ Passed

MOT #11	2020-10-17 14:04
MOT test number	305152042998
Result	✓ Passed
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #10** 2019-10-21 14:50**MOT test number** 275998022107**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))**Advice** Offside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #9** 2019-04-22 17:08**MOT test number** 735104584713**Result** ✓ Passed**MOT #8** 2019-04-22 11:35**MOT test number** 482370675037**Result** ✗ Failed**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Front Brake pedal has insufficient reserve travel (1.1.2 (a))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Front Brake pedal has insufficient reserve travel (1.1.2 (a))**MOT #7** 2018-10-22 09:47**MOT test number** 977918023503**Result** ✓ Passed**MOT #6** 2018-08-15 12:37**MOT test number** 335915805140**Result** ✓ Passed**Advice** Rear brake discs corroded

**MOT #5** 2017-08-16 12:26**MOT test number** 713460702190**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Slight corrosion to rear brake discs**MOT #4** 2016-08-08 12:49**MOT test number** 961847327814**Result** ✓ Passed**Advice** Rear nearside and offside tyre perishing**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #3** 2015-08-21 15:05**MOT test number** 540487114570**Result** ✓ Passed**MOT #2** 2014-12-31 08:21**MOT test number** 585625364327**Result** ✓ Passed**MOT #1** 2014-12-29 11:33**MOT test number** 525383364340**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
22 October 2024

Tax status	Valid until 1 May
Days left	1
MOT expiry date	22 October 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	<b>LB61HXZ</b>
Plate since	2019-09-28
Current registration	<b>LB61HXZ</b>
Plate since	2019-09-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-01-19
Last registration	2023-10-23
Complete history	<a href="#">See info</a>



Registration #1	2012-01-19	17 mi
Registration #2	2014-12-29	24.755 mi
Registration #3	2014-12-31	24.755 mi
Registration #4	2015-08-21	26.409 mi
Registration #5	2016-08-08	38.306 mi
Registration #6	2017-08-16	47.377 mi
Registration #7	2018-08-15	54.061 mi
Registration #8	2018-10-22	54.099 mi
Registration #9	2019-05-20	55.000 mi
Registration #10	2019-05-20	55.000 mi
Registration #11	2019-05-20	55.000 mi
Registration #12	2019-05-20	55.000 mi
Registration #13	2019-05-20	55.000 mi
Registration #14	2019-05-20	55.000 mi
Registration #15	2019-05-20	55.000 mi
Registration #16	2019-05-20	55.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 2023931