



report date: 2024-03-29

## General information

Make	VOLVO
Model	S40 S S40
Colour	Black
Year of manufacture	2007
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H





## MOT history

MOT expiry date	2025-03-31
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #16	2024-03-31 11:09
MOT test number	420743045070
Result	✓ Passed
Next expiry date	2025-03-31
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15	2023-04-01 08:49
MOT test number	981260886107
Result	✓ Passed
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14	2023-04-01 08:49
MOT test number	411733727546
Result	✗ Failed
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))

**MOT #13** 2021-09-03 13:46**MOT test number** 256459661675**Result** ✓ Passed**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Front Coil spring worn (5.3.1 (b) (i))**MOT #12** 2020-09-03 09:48**MOT test number** 922245824523**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2019-08-17 10:43**MOT test number** 454363257229**Result** ✓ Passed**MOT #10** 2018-03-05 11:05**MOT test number** 551586662578**Result** ✓ Passed**MOT #9** 2017-03-06 15:44**MOT test number** 358891510848**Result** ✓ Passed**MOT #8** 2017-03-06 13:57**MOT test number** 567139610062**Result** ✗ Failed**Fail** Nearside Steering rack gaiter split (2.2.D.2d)



<b>MOT #7</b>	2016-03-07 12:26
---------------	------------------

<b>MOT test number</b>	915370838657
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2015-03-05 09:32
---------------	------------------

<b>MOT test number</b>	678254565002
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Engine covers fitted obscuring some components in the engine bay
---------------	--

<b>MOT #5</b>	2014-03-06 12:32
---------------	------------------

<b>MOT test number</b>	936225564026
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2013-03-05 13:30
---------------	------------------

<b>MOT test number</b>	835114863043
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2012-03-05 14:33
---------------	------------------

<b>MOT test number</b>	138085062485
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2011-03-14 12:41
---------------	------------------

<b>MOT test number</b>	905083771077
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2010-03-16 11:40
---------------	------------------

<b>MOT test number</b>	664155670075
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
31 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	31 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-03-30
Last registration	2024-03-31
Complete history	<a href="#">See info</a>



Registration #1	2007-03-30	20 mi
Registration #2	2010-03-16	10.257 mi
Registration #3	2011-03-14	12.756 mi
Registration #4	2012-03-05	14.795 mi
Registration #5	2013-03-05	18.281 mi
Registration #6	2014-03-06	21.333 mi
Registration #7	2015-03-05	24.377 mi
Registration #8	2016-03-07	27.145 mi
Registration #9	2017-03-06	30.890 mi
Registration #10	2018-03-06	35.377 mi
Registration #11	2019-03-06	39.864 mi
Registration #12	2020-03-06	44.351 mi
Registration #13	2021-03-06	48.838 mi
Registration #14	2022-03-06	53.325 mi
Registration #15	2023-03-06	57.812 mi
Registration #16	2024-03-06	62.299 mi
Registration #17	2024-03-31	66.786 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1376 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	70590