




report date: 2024-11-08

General information

Make	MINI
Model	COOPER D LONDON 2012 EDITION
Colour	Red
Year of manufacture	2012
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2023-12-14
Pictures	8



source: g3remarketing.co.uk



MOT history

MOT expiry date	2025-03-26
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	34
Total items failed	7

MOT #14 2024-03-25 16:51

MOT test number 877230977714

Result ✔ Passed

Next expiry date 2025-03-26

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush split slight knock (5.3.4 (a) (i))
- Minor** Offside Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Advice** Exhaust front flexi broken, slight blow
- Advice** Soot visible on engine



MOT #13	2024-03-25 09:56
MOT test number	896000776009
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge worn on shoulders, below 1mm, 2/3mm across (5.2.3 (e))
Minor	Offside Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
Advice	Exhaust front flexi broken, slight blow
Fail	Nearside Rear Valve stem seriously damaged (5.2.3 (j))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush split slight knock (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge worn on shoulders, bald, 2/2.8mm across 205/45/17 (5.2.3 (e))
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Soot visible on engine
Fail	Offside Rear Valve stem seriously damaged (5.2.3 (j))

MOT #12	2023-03-27 14:31
MOT test number	514423388475
Result	✓ Passed

MOT #11	2022-01-10 13:08
MOT test number	139229429522
Result	✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))



MOT #10	2022-01-10 11:31
MOT test number	435201732768
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2020-12-18 09:46
MOT test number	106226548435
Result	✓ Passed

MOT #8	2020-01-17 14:05
MOT test number	634668114920
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2020-01-17 14:05
MOT test number	162737406479
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))



MOT #6 2018-09-12 08:55

MOT test number 411773338586

Result ✓ Passed

Advice Vehicle fitted with undertrays which prevent the inspection of certain items

MOT #5 2017-10-04 09:39

MOT test number 207419341805

Result ✓ Passed

Advice Engine covers fitted obscuring some components in the engine bay.

Advice Under trays fitted obscuring some under side components.

MOT #4 2017-10-03 08:22

MOT test number 345444098344

Result ✗ Failed

Advice Engine covers fitted obscuring some components in the engine bay.

Fail Rear Brakes imbalanced across an axle (3.7.B.5b)

Advice Under trays fitted obscuring some under side components.

Advice Front tyres are non run flats , rear tyres are run flats.

MOT #3 2017-04-10 10:00

MOT test number 327785489845

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit outer edge balding (4.1.E.1)

Advice Front brake pads low

Advice Nearside Front Tyre worn close to the legal limit outer edge balding (4.1.E.1)



MOT #2 2016-04-25 11:55

MOT test number 599893690026

Result ✔ Passed

- Advice** Engine covers fitted obscuring some components
- Advice** Nearside Rear Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Under trays fitted obscuring some components
- Advice** Offside Rear Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1 2015-05-20 09:27

MOT test number 377160345167

Result ✔ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
26 March 2025

Tax status	Valid until 1 April
Days left	113
MOT expiry date	26 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YX12JVM
Plate since	2019-09-29
Current registration	YX12JVM
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-22
Last registration	2024-03-25
Complete history	See info



Registration #1	2012-06-22	24 mi
Registration #2	2015-05-20	33.507 mi
Registration #3	2016-04-25	37.597 mi
Registration #4	2017-04-10	40.777 mi
Registration #5	2017-10-03	41.903 mi
Registration #6	2017-10-04	41.916 mi
Registration #7	2018-09-12	50.116 mi
Registration #8	2020-01-17	61.309 mi
Registration #9	2020-01-17	61.309 mi
Registration #10	2020-01-17	61.309 mi
Registration #11	2020-01-17	61.309 mi
Registration #12	2020-01-17	61.309 mi
Registration #13	2020-01-17	61.309 mi
Registration #14	2020-01-17	61.309 mi
Registration #15	2020-01-17	61.309 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	70558158