




report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE S
Colour	Grey
Year of manufacture	-
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	360 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-31
Pictures	9
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT #14	2022-07-02 17:09
MOT test number	530409208667
Result	✓ Passed
Next expiry date	2023-07-05
Advice	Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear undercarriage rusty
Advice	Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #13	2022-07-02 17:09
MOT test number	239848695569
Result	✗ Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Rear undercarriage rusty
Advice	Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12** 2021-07-06 09:51**MOT test number** 757652490863**Result** ✓ Passed**Advice** Rear Shock absorbers light misting of oil or has limited damping effect both sides (5.3.2 (b))**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))**MOT #11** 2021-07-05 17:04**MOT test number** 458191572794**Result** ✗ Failed**Fail** Offside Front Lower Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))**Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Shock absorbers light misting of oil or has limited damping effect both sides (5.3.2 (b))**MOT #10** 2019-10-04 08:23**MOT test number** 944409211820**Result** ✓ Passed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #9** 2018-09-28 11:51**MOT test number** 794199018396**Result** ✓ Passed

**MOT #8** 2018-09-28 10:29**MOT test number** 541069058044**Result** ✗ Failed**Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))**Fail** Offside Rear Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))**MOT #7** 2017-09-18 07:55**MOT test number** 393708233419**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner edge,s (3.5.1i)**MOT #6** 2016-10-08 09:23**MOT test number** 960298837640**Result** ✓ Passed**Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #5** 2015-10-03 10:57**MOT test number** 911646379109**Result** ✓ Passed**MOT #4** 2014-10-08 09:07**MOT test number** 539351284222**Result** ✓ Passed

**MOT #3** 2013-09-25 11:45**MOT test number** 467798663246**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2012-07-17 09:40**MOT test number** 996469792151**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2011-07-21 11:22**MOT test number** 268072601255**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-07-31
Last registration	2022-07-02
Complete history	See info



Registration #1	2008-07-31	25 mi
Registration #2	2011-07-21	34.041 mi
Registration #3	2012-07-17	42.473 mi
Registration #4	2013-09-25	49.219 mi
Registration #5	2014-10-08	60.075 mi
Registration #6	2015-10-03	68.679 mi
Registration #7	2016-10-08	77.924 mi
Registration #8	2017-09-18	88.492 mi
Registration #9	2018-09-18	99.060 mi
Registration #10	2019-09-18	109.628 mi
Registration #11	2020-09-18	120.196 mi
Registration #12	2021-09-18	130.764 mi
Registration #13	2022-07-02	141.332 mi
Registration #14	2023-07-02	151.900 mi
Registration #15	2024-03-29	162.468 mi
Registration #16	2024-03-29	173.036 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	080122102651BG