



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EASY
Colour	White
Year of manufacture	2012
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-07-02
Pictures	27
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-12
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	34
Total items failed	10

MOT #12	2023-07-07 15:55
MOT test number	917818101044
Result	✓ Passed
Next expiry date	2024-07-12
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Exhaust has a minor leak of exhaust gases centre pipe joint (6.1.2 (a))
Advice	Exhaust mounting defective front pipe clamp (6.1.2 (a))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Items removed from driver's view prior to test
Advice	Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2023-07-07 08:56

MOT test number

323579606719

Result**✗ Failed**

- Advice** Exhaust has a minor leak of exhaust gases centre pipe joint (6.1.2 (a))
- Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Front Anti-roll bar linkage missing (5.3.3 (a) (ii))
- Advice** Exhaust mounting defective front pipe clamp (6.1.2 (a))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (ii))
- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Front Anti-roll bar missing (5.3.3 (a) (ii))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage missing (5.3.3 (a) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #10** 2022-06-28 12:06**MOT test number** 127416256187**Result** ✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Items removed from driver's view prior to test
- Advice** Exhaust has a minor leak of exhaust gases back box joint (6.1.2 (a))

MOT #9 2021-07-13 12:10**MOT test number** 872370975062**Result** ✓ Passed**MOT #8** 2020-10-27 12:03**MOT test number** 264875800655**Result** ✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2019-10-01 14:02**MOT test number** 235145566940**Result** ✓ Passed**MOT #6** 2018-12-05 09:58**MOT test number** 415176232274**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Below 1.6mm raised, 3mm centre (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #5**

2018-12-05 09:38

MOT test number

405479355255

Result**✗ Failed****Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Below 1.6mm raised, 3mm centre (5.2.3 (e))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #4**

2017-12-06 15:41

MOT test number

439232809288

Result**✓ Passed****Advice** Coil spring corroded ALL (2.4.C.1b)**Advice** Exhaust corroded**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3**

2016-12-07 11:43

MOT test number

749191636899

Result**✓ Passed**



MOT #2	2016-12-07 11:37
MOT test number	366050347761
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Front Brake pad(s) wearing thin BOTH (3.5.1g)

MOT #1	2015-11-25 11:56
MOT test number	487117201322
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
12 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	12 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-29
Last registration	2023-07-07
Complete history	See info



Registration #1	2012-09-29	12 mi
Registration #2	2015-11-25	25.097 mi
Registration #3	2016-12-07	35.549 mi
Registration #4	2016-12-07	35.549 mi
Registration #5	2017-12-06	42.775 mi
Registration #6	2018-12-05	49.730 mi
Registration #7	2018-12-05	49.730 mi
Registration #8	2019-05-29	55.277 mi
Registration #9	2019-05-29	55.277 mi
Registration #10	2019-05-29	55.277 mi
Registration #11	2019-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi
Registration #14	2019-05-29	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number 0207966