





report date: 2024-03-29

General information

Make	FIAT
Model	500 L MULTIJET TREKKING DUALOGIC
Colour	Yellow
Year of manufacture	2014
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	72.4 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/13



Internet history

Entry 1


Date 2021-05-22

Pictures 27

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-09-17
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	22
Total items failed	5

MOT #12		2023-09-18 13:57
MOT test	number	542010402831
Result		✓ Passed
Next expi	ry date	2024-09-17
Advice	Central Front Exhaust mounting defective (6.1.2 (a))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))

MOT #11		2023-09-11 10:27
MOT test	number	475078884661
Result		× Failed
Advice	Central Front Exhaust mounting defective (6.1.2 (a))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weaken	ned (1.1.14 (a) (ii))
Fail Of	fside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Fail Windscreen washer not working (3.5 (a))		

CarCheck.co.uk page 3/13



report date: 2024-03-29

 MOT #10
 2022-04-25 10:53

 MOT test number
 239904059269

 Result
 ✓ Passed

 MOT #9
 2022-04-20 11:22

 MOT test number
 889767807505

 Result
 X Failed

 Fail
 Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #8

MOT test number

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2020-10-29 11:24 376860676429 **MOT test number** Result Passed MOT #6 2019-10-31 13:40 **MOT test number** 886866061384 Result Passed MOT #5 2019-10-31 11:36 377298591665 **MOT test number** Result × Failed

Fail Tyre tread depth below requirements of 1.6mm both front (5.2.3 (e))

CarCheck.co.uk page 4/13



MOT #4 2018-10-23 09:21

MOT test number 644537559060

Result ✓ Passed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3 2017-10-09 10:47

MOT test number 669155190509

Result \sqrt{Passed}

Advice Offside Front Tyre worn close to the legal limit (4.1.E.2b)

Advice Offside Rear Inner Tyre worn close to the legal limit (4.1.E.2b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.2b)

Advice Both front tyres have tread pealing on inner and outer edge

Advice Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.2b)

MOT #2 2016-11-01 15:01

MOT test number 318241185575

Advice Both front wipers smearing


Advice Signs of fuel leak from injector area no visible leak at time of test

Advice Nearside rear tyre feathered on inner edge

CarCheck.co.uk page 5/13



report date: 2024-03-29



CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check





Expires: 17 September 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	17 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

ST63VSP

report date: 2024-03-29

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-01-24
Last registration	2023-09-18
Complete history	See info



Registration #1	2014-01-24	18 mi
Registration #2	2016-11-01	51.779 mi
Registration #3	2016-11-01	51.779 mi
Registration #4	2017-10-09	63.182 mi
Registration #5	2018-10-23	76.613 mi
Registration #6	2019-10-31	88.620 mi
Registration #7	2019-10-31	88.622 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2018 mm
Height	1679 mm
Length	4270 mm
Kerb weight	1320 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

5423180