





report date: 2024-03-29

## General information

Make	SUBARU
Model	LEGACY D S
Colour	Red
Year of manufacture	2012
Top speed	126 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.800 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	161 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-06-12

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-06-12
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #11	2023-06-01 10:37
MOT test number	254834035000
Result	✓ Passed
Next expiry date	2024-06-12
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened showing signs of overheating (1.1.14 (a) (ii))	
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #10		2022-06-13 15:57
MOT test	number	360763702758
Result		✓ Passed
Advice	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice Front Suspension arm pin or bush worn but not resulting in excessive movement o/s n/s (5.3.4 (a) (i))		

MOT #9	2021-06-12 11:54
MOT test number	883456475424
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



**MOT #8** 

BF12YEY report date: 2024-03-29

2020-10-13 10:26

MOT test number 815771377325

**Result** ✓ Passed

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Cut across tread, inner edge. (5.2.3 (d) (i))

MOT #7 2019-05-25 08:25

MOT test number 512980634543

Result \rightarrow Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking around primary grooves. (5.2.3 (d) (ii))

MOT #6 2018-05-18 10:13

MOT test number 457745538743

Result 

Passed

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5 2017-05-30 13:26

**MOT test number** 819384224597

Result 

Passed

MOT #4 2016-05-20 11:42

**MOT test number** 652032223463

**Result** 
✓ Passed

MOT #3 2015-05-30 12:21

**MOT test number** 489660655139

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 4/12



BF12YEY

report date: 2024-03-29

MOT #2		2015-03-04 10:42
MOT test number		658993565080
Result		<b>✓</b> Passed
MOT #1		2015-03-04 10:42
MOT test number		727983465003
Result		<b>×</b> Failed
Pass with rectification	Offside Headlamp aim too high (1.8)	
Pass with rectification	Nearside Headlamp aim too high (1.8)	

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	12 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this SUBARU. See if, where and when this SUBARU had damage and the car repair costs. We also check if this SUBARU was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra SUBARU salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this SUBARU in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this SUBARU? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		ARU
***************************************		
THE PARTY OF THE P		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this SUBARU had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this SUBARU is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUBARU has been settled.

If not, and you buy this SUBARU then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUBARU is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-04-11
Last registration	2023-06-01
Complete history	See info



Registration #1	2012-04-11	16 mi
Registration #2	2015-03-04	33.743 mi
Registration #3	2015-05-30	36.297 mi
Registration #4	2016-05-20	45.776 mi
Registration #5	2017-05-30	59.910 mi
Registration #6	2018-05-18	79.514 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	58%
Safety systems	71%
Overall rating	73%
Video	see crash video



# Dimensions & weight

Width	1780 mm
Height	1535 mm
Length	4775 mm
Wheel base	2750 mm
Kerb weight	1558 kg
Max. allowed weight	2075 kg

# Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	430095

CarCheck.co.uk page 12/12