



report date: 2024-03-29

General information

Make	CITROEN
Model	SAXO LX
Colour	Silver
Year of manufacture	2000
Top speed	101 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	88 Nm at 3.800 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	43.5 mpg




LABEL UNKNOWN



Internet history

Entry 2


Date	2022-07-24
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2022-01-21
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-01-10
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	7
Total items failed	13

MOT #25 2023-12-18 11:44

MOT test number 119306759333

Result ✓ Passed

Next expiry date 2025-01-10

- Advice** Condensation in both rear lamps.
- Advice** Rear Tyre slightly damaged/cracking or perishing Both rear tyres perished. (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Side repeater slightly discoloured Both side repeaters discoloured. (4.4.3 (a))

MOT #24 2023-01-11 11:19

MOT test number 598382107393

Result ✓ Passed

MOT #23 2021-06-16 13:01

MOT test number 176613050742

Result ✓ Passed

**MOT #22** 2021-06-09 09:40**MOT test number** 161671987176**Result** ✗ Failed**Fail** Offside Front Anti-roll bar attachment bracket/mounting fractured (5.3.3 (b) (ii))**MOT #21** 2020-06-12 09:40**MOT test number** 627733501190**Result** ✓ Passed**MOT #20** 2019-06-17 09:34**MOT test number** 367518017051**Result** ✓ Passed**MOT #19** 2018-06-11 09:47**MOT test number** 925089060180**Result** ✓ Passed**MOT #18** 2017-06-21 09:45**MOT test number** 973938066270**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #17** 2017-06-21 09:45**MOT test number** 887774806968**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)



MOT #16	2016-06-21 10:06
----------------	------------------

MOT test number	859104487567
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #15	2015-06-11 11:09
----------------	------------------

MOT test number	356332965107
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #14	2014-06-18 11:48
----------------	------------------

MOT test number	145929164166
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #13	2013-12-03 08:45
----------------	------------------

MOT test number	285287033372
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2013-12-03 08:45
----------------	------------------

MOT test number	957417733321
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
--------------------------------	---

Pass with rectification	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
--------------------------------	--

MOT #11	2012-12-13 15:51
----------------	------------------

MOT test number	205288142381
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #10** 2012-12-12 13:37**MOT test number** 685097642328**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Spare wheel carrier insecure (6.4.2)**MOT #9** 2011-06-10 08:08**MOT test number** 965771861125**Result** ✓ Passed**MOT #8** 2010-06-29 16:13**MOT test number** 551310380110**Result** ✓ Passed**MOT #7** 2010-06-28 11:44**MOT test number** 990629170131**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #6** 2009-06-08 13:00**MOT test number** 660949059150**Result** ✓ Passed

**MOT #5** 2009-06-08 11:54**MOT test number** 963579059155**Result** ✗ Failed**Fail** Offside Outer Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Outer Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #4** 2008-06-02 16:49**MOT test number** 753884558119**Result** ✓ Passed**MOT #3** 2007-06-22 10:30**MOT test number** 612313977115**Result** ✓ Passed**MOT #2** 2007-06-22 10:30**MOT test number** 394373577152**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #1** 2006-06-19 11:39**MOT test number** 271450276411**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
10 January 2025

Tax status	Valid until 1 January
------------	-----------------------

Days left	247
-----------	-----

MOT expiry date	10 January 2025
-----------------	-----------------

Full MOT history	See MOT history
------------------	---------------------------------



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2000-07-28
Last registration	2023-12-18
Complete history	See info



Registration #1	2000-07-28	24 mi
Registration #2	2006-06-19	5.461 mi
Registration #3	2007-06-22	6.223 mi
Registration #4	2008-06-02	6.802 mi
Registration #5	2009-06-08	7.175 mi
Registration #6	2009-06-08	7.175 mi
Registration #7	2010-06-28	7.419 mi
Registration #8	2010-06-29	7.436 mi
Registration #9	2011-06-10	8.934 mi
Registration #10	2012-12-12	9.246 mi
Registration #11	2012-12-13	9.246 mi
Registration #12	2013-12-03	9.880 mi
Registration #13	2014-06-18	10.127 mi
Registration #14	2015-06-22	10.377 mi
Registration #15	2016-06-22	10.377 mi
Registration #16	2017-06-22	10.377 mi
Registration #17	2018-06-22	10.377 mi
Registration #18	2019-06-22	10.377 mi
Registration #19	2020-06-22	10.377 mi
Registration #20	2021-06-22	10.377 mi
Registration #21	2022-06-22	10.377 mi
Registration #22	2023-06-22	10.377 mi
Registration #23	2024-06-22	10.377 mi
Registration #24	2025-06-22	10.377 mi
Registration #25	2026-06-22	10.377 mi
Registration #26	2027-06-22	10.377 mi

More info >



Safety ratings

NCAP rating ★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1595 mm
Height	1360 mm
Length	3718 mm
Wheel base	2385 mm
Kerb weight	805 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Single-Point Injection
Number of doors	3
Number of axles	2
Engine number	FP4X3256284