



General information

Make	FORD
Model	FUSION TITANIUM
Colour	Blue
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	128 Nm at 4.200 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





## Internet history

## Entry 5

Date 2023-01-24

Pictures 8

Listing price [View report](#)

source: cargurus.co.uk



## Entry 4

Date 2023-01-23

Pictures 8

Listing price [View report](#)



source: autotrader.co.uk



## Entry 3

Date 2022-02-14

Pictures 11

Listing price [View report](#)

source: autotrader.co.uk

## Entry 2


Date 2022-01-06  
CarCheck.co.uk

Pictures

11

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date

2021-10-05

Pictures

11

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-30
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	24
Total items failed	9

MOT #16	2024-01-12 09:01
MOT test number	914669389492
Result	✓ Passed
Next expiry date	2025-01-30

MOT #15	2023-01-31 16:57
MOT test number	965755372045
Result	✓ Passed

MOT #14	2022-09-14 15:42
MOT test number	801109402337
Result	✓ Passed
Advice	Front Brake disc worn, but not excessively both side (1.1.14 (a) (i))
Advice	Exhaust system rusty condition
Advice	Car underneath corrosion

**MOT #13** 2021-09-16 12:23**MOT test number** 249209544278**Result** ✓ Passed

- Advice** Exhaust system in rusty condition
- Advice** Under body slightly corrosion on surface
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**MOT #12** 2021-09-16 12:22**MOT test number** 921652838637**Result** ✗ Failed

- Advice** Exhaust system in rusty condition
- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Under body slightly corrosion on surface
- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively both sides (3.4 (b) (ii))

**MOT #11** 2020-08-21 11:31**MOT test number** 878020270233**Result** ✓ Passed**MOT #10** 2019-08-09 15:04**MOT test number** 453289581405**Result** ✓ Passed

**MOT #9** 2019-08-09 09:01**MOT test number** 676253423604**Result** ✗ Failed**Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Front Brake disc worn, but not excessively badly corroded on inner faces (1.1.14 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm 195x60x15 (5.2.3 (e))**MOT #8** 2018-08-13 15:54**MOT test number** 787670051702**Result** ✓ Passed**Advice** Front brake discs corroded on braking faces**MOT #7** 2018-08-13 13:07**MOT test number** 446280288842**Result** ✗ Failed**Advice** Water in both rear lamps**Fail** Windscreen wiper does not clear the windscreen effectively both sides (3.4 (b) (ii))**Fail** Rear Exhaust silencer insecure (8.1.1 (b) (i))**Advice** Front brake discs corroded on braking faces**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

**MOT #6** 2017-08-14 09:38**MOT test number** 470544019815**Result** ✓ Passed

- Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened pitted on inner face (3.5.1i)
- Advice** Rear both rear tyres worn low + perished.
- Advice** Rear Direction indicator slightly discoloured both (1.4.A.2f)

**MOT #5** 2017-08-14 09:37**MOT test number** 429961942307**Result** ✗ Failed

- Advice** Rear both rear tyres worn low + perished.
- Advice** Rear Direction indicator slightly discoloured both (1.4.A.2f)
- Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Pass with rectification** Central Stop lamp not working (1.2.1b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened pitted on inner face (3.5.1i)

**MOT #4** 2016-08-15 09:04**MOT test number** 790406434908**Result** ✓ Passed**MOT #3** 2016-08-15 08:42**MOT test number** 206702739772**Result** ✗ Failed

- Fail** Windscreen wiper does not clear the windscreen effectively both (8.2.2)



MOT #2	2015-08-17 13:20
MOT test number	356599725430
Result	✓ Passed
Notice	Nail in nearside front tyre
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Notice	Front tyres getting low on tread 195/60/15

MOT #1	2014-08-22 15:52
MOT test number	785944434215
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
30 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	30 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2011-05-11
Last registration	2024-01-12
Complete history	<a href="#">See info</a>



Registration #1	2011-05-11	28 mi
Registration #2	2014-08-22	29.405 mi
Registration #3	2015-08-17	36.501 mi
Registration #4	2016-08-15	44.486 mi
Registration #5	2016-08-15	44.486 mi
Registration #6	2017-08-14	53.057 mi
Registration #7	2017-08-14	53.057 mi
Registration #8	2018-08-13	61.113 mi
Registration #9	2018-08-13	61.114 mi
Registration #10	2019-08-09	69.255 mi
Registration #11	2019-08-09	69.255 mi
Registration #12	2019-08-09	69.255 mi
Registration #13	2019-08-09	69.255 mi
Registration #14	2019-08-09	69.255 mi
Registration #15	2019-08-09	69.255 mi
Registration #16	2019-08-09	69.255 mi
Registration #17	2019-08-09	69.255 mi
Registration #18	2019-08-09	69.255 mi
Registration #19	2019-08-09	69.255 mi
Registration #20	2019-08-09	69.255 mi
Registration #21	2019-08-09	69.255 mi
Registration #22	2019-08-09	69.255 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1722 mm
Height	1433 mm
Length	3950 mm
Wheel base	2489 mm
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

