





report date: 2024-03-29

General information

| Make | RENAULT |
|---------------------|-------------------------|
| Model | MEGANE RENAULTSPORT S/S |
| Colour | Grey |
| Year of manufacture | 2014 |
| Top speed | 158 mph |
| 0 - 60 mph | 6.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 265 BHP |
|-------------------------|---------------------|
| Max. torque | 360 Nm at 3.000 rpm |
| Engine capacity | 1.998 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 28.8 mpg |
| Consumption extra urban | 45.6 mpg |
| Consumption combined | 37.7 mpg |
| CO2 emission | 174 g/km |
| CO2 label | Н |



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-12-19


Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

| B 4 | \sim $-$ | | |
|-------|-------------|------|--------|
| 10.71 | $^{\prime}$ | hic | tory |
| 101 | C I | 1115 | I OI V |
| | • | | , |

| MOT expiry date | 2024-09-05 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 4 |
| Total items failed | 7 |

| MOT #10 | 2023-09-05 12:43 |
|------------------|------------------|
| MOT test number | 705394893077 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-05 |

| MOT #9 | 2022-09-06 18:32 |
|-----------------|------------------|
| MOT test number | 432658191362 |
| Result | √ Passed |

| MOT #8 | 2022-08-23 13:30 |
|-----------------|------------------|
| MOT test number | 232662029501 |

Result × Failed

Advice Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail Offside Rear Brake pipe excessively corroded flexy hose (1.1.11 (c))

Advice Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))

Fail Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

Fail Nearside Rear Brake pipe excessively corroded flexy hose (1.1.11 (c))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2021-09-02 14:42

MOT test number 290963245071

MOT #6 2020-11-25 14:39

MOT test number 628349886354

Result ✓ Passed

MOT #5 2020-11-18 17:03

MOT test number 852789988907

Result X Failed

Fail Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #4 2019-11-11 16:10

MOT test number 547530663953

Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #3 2019-02-08 11:37

MOT test number 990469869293

Result
✓ Passed

MOT #2 2018-02-09 09:44

MOT test number 199056832377

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1

MOT test number

921644379825

Result

Advice Covers fitted obscuring some components in engine bay

CarCheck.co.uk page 5/12



SW14LHO report date: 2024-03-29

Tax & MOT check





Expires: 5 September 2024

| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 5 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | Н |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



SW14LHO report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

SW14LHO

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this RENAULT had different number plates. ober of plates

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| 0.1.116 | |

Contact info

More info >


CarCheck.co.uk page 10/12



SW14LHO report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2014-06-02 |
| Last registration | 2023-09-05 |
| Complete history | See info |



| Registration #1 | 2014-06-02 | 14 mi |
|------------------|------------|-----------|
| Registration #2 | 2017-02-10 | 10.459 mi |
| Registration #3 | 2018-02-09 | 19.030 mi |
| Registration #4 | 2019-02-08 | 26.487 mi |
| Registration #5 | 2019-11-11 | 33.596 mi |
| Registration #6 | 2020-11-18 | 40.016 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 83% |
| Children | 78% |
| Pedestrian | 60% |
| Safety systems | 48% |
| Overall rating | 71% |
| Video | see crash video |



Dimensions & weight

| Width | 1848 mm |
|---------------------|---------|
| Height | 1435 mm |
| Length | 4299 mm |
| Wheel base | 2636 mm |
| Kerb weight | 1394 kg |
| Max. allowed weight | 1887 kg |

Additional information

| Fuel tank capacity | 60 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

Number of axles2Engine numberC024660