



report date: 2024-03-28

## General information

Make	VOLVO
Model	XC70 XC70 D5 AWD SE EU4
Colour	Purple
Year of manufacture	2006
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-09-08
Pictures	22
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2023-09-13
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	35
Total items failed	13

MOT #18	2022-08-22 10:03
MOT test number	422161428480
Result	✓ Passed
Next expiry date	2023-09-13

MOT #17	2021-09-14 14:25
MOT test number	849205737131
Result	✓ Passed

MOT #16	2021-09-13 09:55
MOT test number	938359297256
Result	✗ Failed

- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Anti-roll bar linkage damaged but not seriously weakened bent/distorted (5.3.3 (b) (i))

**MOT #15** 2020-12-05 12:49**MOT test number** 101769550752**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #14** 2019-05-31 07:56**MOT test number** 115249252924**Result** ✓ Passed**Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Tyre slightly damaged/cracking or perishing all tyres (5.2.3 (d) (ii))**MOT #13** 2018-05-29 09:29**MOT test number** 417817142122**Result** ✓ Passed**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Brake hose slightly twisted (1.1.12 (b) (i))**Advice** Exhaust mounting defective (6.1.2 (a))**Advice** Both rear brake hoses slightly deteriorated

**MOT #12** 2017-06-26 10:47**MOT test number** 202328831849**Result** ✓ Passed**MOT #11** 2016-04-29 15:13**MOT test number** 427442844847**Result** ✓ Passed**Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front tyre low on inner and outer edges**MOT #10** 2015-07-17 16:09**MOT test number** 996048695165**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2015-07-16 09:24**MOT test number** 228487195190**Result** ✗ Failed**Fail** Nearside Front Brake hose excessively deteriorated (3.6.B.4d)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Brake hose excessively deteriorated (3.6.B.4d)**Fail** Offside Rear Upper Rear position lamp(s) not working (1.1.A.3b)



<b>MOT #8</b>	2014-07-17 15:22
<b>MOT test number</b>	706348894126
<b>Result</b>	✓ Passed
<b>Advice</b>	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #7</b>	2013-07-08 14:58
<b>MOT test number</b>	775049083184
<b>Result</b>	✓ Passed
<b>Notice</b>	Exhaust bracket broken
<b>Notice</b>	Rear tyres worn 2 to 3mm tread
<b>Notice</b>	O/s front abs ring cracked

<b>MOT #6</b>	2012-07-16 12:15
<b>MOT test number</b>	528098592176
<b>Result</b>	✓ Passed
<b>Notice</b>	Exhaust mid section rear mount broken
<b>Notice</b>	Plastic sill covers fitted

<b>MOT #5</b>	2011-06-16 16:08
<b>MOT test number</b>	128547161179
<b>Result</b>	✓ Passed
<b>Notice</b>	BOTH FRONT BRAKE HOSES CRACKING SLIGHTLY
<b>Notice</b>	HANDBRAKE LEVER HAS SLIGHT TRAVEL

**MOT #4** 2011-06-15 14:28**MOT test number** 976686261144**Result** ✗ Failed**Notice** BOTH FRONT BRAKE HOSES CRACKING SLIGHTLY**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** HANDBRAKE LEVER HAS SLIGHT TRAVEL**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #3** 2010-06-11 16:28**MOT test number** 882822260176**Result** ✓ Passed**Notice** Front brake pads may be getting low**Notice** Rear brake discs rusty**MOT #2** 2010-06-11 16:28**MOT test number** 260222060183**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Rear brake discs rusty**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Front brake pads may be getting low**MOT #1** 2009-05-11 14:56**MOT test number** 371431639111**Result** ✓ Passed**Notice** Plastic sill covers fitted



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>OV06YHW</b>
Plate since	2019-06-28
Current registration	<b>OV06YHW</b>
Plate since	2019-06-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-05-11
Last registration	2022-08-22
Complete history	<a href="#">See info</a>



Registration #1	2006-05-11	26 mi
Registration #2	2009-05-11	46.643 mi
Registration #3	2010-06-11	62.144 mi
Registration #4	2011-06-15	82.626 mi
Registration #5	2011-06-16	82.677 mi
Registration #6	2012-07-16	100.244 mi
Registration #7	2013-07-08	115.695 mi
Registration #8	2014-07-17	127.648 mi
Registration #9	2015-07-16	131.353 mi
Registration #10	2015-07-17	131.354 mi
Registration #11	2016-05-20	151.377 mi
Registration #12	2016-05-20	151.377 mi
Registration #13	2016-05-20	151.377 mi
Registration #14	2016-05-20	151.377 mi
Registration #15	2016-05-20	151.377 mi
Registration #16	2016-05-20	151.377 mi
Registration #17	2016-05-20	151.377 mi
Registration #18	2016-05-20	151.377 mi
Registration #19	2016-05-20	151.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2100 mm
Height	1562 mm
Length	4733 mm
Wheel base	2763 mm
Kerb weight	1719 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	363695