



SLIIBZV

report date: 2024-03-28

General information

Make	MAZDA
Model	2 TS2
Colour	White
Year of manufacture	2011
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	122 Nm at 3.500 rpm
Engine capacity	1.349 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 2

Date	2023-08-22
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

Entry 1

Date	2021-06-17
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-09-07
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	15
Total items failed	1

MOT #14	2023-09-08 13:59
MOT test number	502769180451
Result	✓ Passed
Next expiry date	2024-09-07

MOT #13	2023-09-04 12:50
MOT test number	726472230009
Result	✗ Failed
<b>MAJOR</b> Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))	

MOT #12	2022-08-10 11:21
MOT test number	997270943224
Result	✓ Passed
<b>Advice</b> Vehicles internal headlight adjuster altered to recheck lights	
<b>Minor</b> Nearside Windscreen wiper blade defective torn (3.4 (b) (i))	
<b>Advice</b> Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
<b>Advice</b> Centre heat shield insecure	
<b>Advice</b> Items removed from driver's view prior to test Air fresheners	
<b>Advice</b> Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
<b>Advice</b> Nearside Front Tyre has a cut but not deep enough to reach the ply or cords damaged on sidewall (5.2.3 (d) (i))	

**MOT #11** 2021-08-11 16:05**MOT test number** 747220878285**Result** ✓ Passed**MOT #10** 2021-02-01 09:17**MOT test number** 738631284075**Result** ✓ Passed**Advice** Slight knock at front**MOT #9** 2020-02-01 10:20**MOT test number** 644427515080**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2019-02-04 13:47**MOT test number** 742816266945**Result** ✓ Passed**MOT #7** 2019-02-01 15:57**MOT test number** 958831320249**Result** ✗ Failed**MAJOR** Nearside Front Inner Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #6** 2018-01-31 16:24**MOT test number** 686413633127**Result** ✓ Passed

**MOT #5** 2017-01-31 13:57**MOT test number** 296651718423**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**MOT #4** 2017-01-21 10:06**MOT test number** 320801693563**Result** ✗ Failed**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2016-01-29 11:37**MOT test number** 623786529567**Result** ✓ Passed**MOT #2** 2015-01-31 10:18**MOT test number** 777211535062**Result** ✓ Passed**Notice** Both rear tyres slightly perished in tread grooves**MOT #1** 2014-02-03 16:59**MOT test number** 208084634018**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
7 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	7 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-17
Last registration	2023-09-08
Complete history	<a href="#">See info</a>



Registration #1	2011-03-17	20 mi
Registration #2	2014-02-03	22.285 mi
Registration #3	2015-01-31	28.430 mi
Registration #4	2016-01-29	35.833 mi
Registration #5	2017-01-21	43.523 mi
Registration #6	2017-01-31	43.523 mi
Registration #7	2018-01-31	51.337 mi
Registration #8	2019-02-01	57.777 mi
Registration #9	2019-02-04	57.785 mi
Registration #10	2019-02-05	57.777 mi
Registration #11	2019-02-05	57.777 mi
Registration #12	2019-02-05	57.777 mi
Registration #13	2019-02-05	57.777 mi
Registration #14	2019-02-05	57.777 mi
Registration #15	2019-02-05	57.777 mi
Registration #16	2019-02-05	57.777 mi
Registration #17	2019-02-05	57.777 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1025 kg
Max. allowed weight	1455 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	ZJ 915524