



PEUGEOT

SH05HFD


report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 GTI
Colour	Silver
Year of manufacture	2005
Top speed	130 mph
0 - 60 mph	8.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	190 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-02
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	29
Total items failed	17

MOT #23	2024-03-03 11:35
MOT test number	863663208899
Result	✓ Passed
Next expiry date	2025-03-02
Advice	Advise front tyers

MOT #22	2023-02-05 13:24
MOT test number	460213507837
Result	✓ Passed
Advice	Advise rear pads

MOT #21	2023-02-05 13:24
MOT test number	933594135284
Result	✗ Failed
Advice	Advise rear pads
Pass with rectification	Front Tyre tread depth below requirements of 1.6mm 2 (5.2.3 (e))
Pass with rectification	Rear Exhaust has a major leak of exhaust gases box reare (6.1.2 (a))

MOT #20	2021-12-11 09:44
MOT test number	189536465827
Result	✓ Passed

**MOT #19**

2020-12-18 13:23

MOT test number

876446674657

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Coil spring corroded n/s and o/s (5.3.1 (b) (i))
- Advice** Central exhaust box covered with exhaust past
- Advice** Offside Front Outer Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Gearbox mounting defective
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18

2020-12-14 17:24

MOT test number

471010303179

Result

✗ Failed

- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Coil spring corroded n/s and o/s (5.3.1 (b) (i))
- Advice** Offside Front Outer Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Gearbox mounting defective
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Central Emissions not tested box due to major leak (8.2.1.2 (d))

**MOT #17**

2020-10-29 13:11

MOT test number

476091325083

Result

✗ Failed

- Advice** Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Gearbox mounting defective
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Battery insecure and likely to fall from carrier (4.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2019-10-26 09:57

MOT test number

879727055552

Result

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Play in steering rack inner joint(s)

MOT #15

2018-10-19 10:01

MOT test number

595411673452

Result

✓ Passed

**MOT #14** 2017-10-24 10:52**MOT test number** 431570539137**Result** ✓ Passed**MOT #13** 2016-10-18 11:42**MOT test number** 740703838013**Result** ✓ Passed**MOT #12** 2016-10-18 10:10**MOT test number** 510996452647**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed tyre wall perished. (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit 1.9 mm (4.1.E.1)**MOT #11** 2015-10-14 09:59**MOT test number** 987045249712**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 2.2 mm (4.1.E.1)**Advice** Nearside windscreen washer jet poor operation.**MOT #10** 2014-10-20 15:47**MOT test number** 377133394246**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2014-10-20 14:20**MOT test number** 237733294200**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2013-10-21 11:55**MOT test number** 429194793204**Result** ✓ Passed**MOT #7** 2012-10-30 13:57**MOT test number** 628564402304**Result** ✓ Passed**Notice** Headlamp masks/converters fitted**MOT #6** 2011-04-18 14:28**MOT test number** 806148601112**Result** ✓ Passed**MOT #5** 2010-04-27 11:11**MOT test number** 453087710119**Result** ✓ Passed**MOT #4** 2010-04-23 13:49**MOT test number** 221303810428**Result** ✗ Failed**Notice** Rear exhaust box corroded**Fail** Rear Exhaust system not adequately supported (7.1.1)



MOT #3	2009-04-23 10:12
MOT test number	712823819120
Result	✓ Passed
MOT #2	2008-04-17 11:38
MOT test number	921718508113
Result	✓ Passed
MOT #1	2008-04-08 12:52
MOT test number	234089198099
Result	✗ Failed
Fail	Nearside Front brake disc excessively pitted (3.5.1h)
Fail	Offside Front brake disc excessively pitted (3.5.1h)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
2 March 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	2 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-04-19
Last registration	2024-03-03
Complete history	See info



Registration #1	2005-04-19	27 mi
Registration #2	2008-04-08	22.222 mi
Registration #3	2008-04-17	22.439 mi
Registration #4	2009-04-23	33.618 mi
Registration #5	2010-04-23	44.433 mi
Registration #6	2010-04-27	44.435 mi
Registration #7	2011-04-18	53.256 mi
Registration #8	2012-10-30	67.613 mi
Registration #9	2013-10-21	76.268 mi
Registration #10	2014-10-20	85.503 mi
Registration #11	2014-10-20	85.503 mi
Registration #12	2015-10-14	95.001 mi
Registration #13	2016-10-18	103.508 mi
Registration #14	2016-10-18	103.508 mi
Registration #15	2016-10-18	103.508 mi
Registration #16	2016-10-18	103.508 mi
Registration #17	2016-10-18	103.508 mi
Registration #18	2016-10-18	103.508 mi
Registration #19	2016-10-18	103.508 mi
Registration #20	2016-10-18	103.508 mi
Registration #21	2016-10-18	103.508 mi
Registration #22	2016-10-18	103.508 mi
Registration #23	2016-10-18	103.508 mi
Registration #24	2016-10-18	103.508 mi
Registration #25	2016-10-18	103.508 mi



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1432 mm
Length	3835 mm
Wheel base	2445 mm
Kerb weight	1050 kg
Max. allowed weight	1560 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	LH3B1206651