



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Black
Year of manufacture	2014
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G







Internet history

Entry 2


Date	2022-02-23
Pictures	47
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2022-01-12
Pictures	24
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-03
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	15
Total items failed	6

## MOT #10 2024-01-30 12:11

MOT test number 155175148399

Result ✓ Passed

Next expiry date 2025-02-03

- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm, Rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm, Rear bush (5.3.4 (a) (i))

## MOT #9 2023-01-27 14:34

MOT test number 963816190696

Result ✓ Passed

- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

## MOT #8 2023-01-27 12:15

MOT test number 392207453409

Result ✗ Failed

- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))



<b>MOT #7</b>	2022-01-20 15:03
<b>MOT test number</b>	898132427509
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Exhaust system slightly corroded.

<b>MOT #6</b>	2021-02-04 15:48
<b>MOT test number</b>	246010637638
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
<b>Advice</b>	Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Child Seat fitted not allowing full inspection of adult belt

<b>MOT #5</b>	2020-01-30 14:52
<b>MOT test number</b>	612318568622
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Tyre worn close to legal limit/worn on edge offside and nearside also perished/cracked (5.2.3 (e))
<b>Advice</b>	Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #4** 2020-01-29 12:11**MOT test number** 202203044760**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Rear Tyre worn close to legal limit/worn on edge offside and nearside also perished/cracked (5.2.3 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Rear Reversing lamp inoperative (4.6.1 (a))**MOT #3** 2019-01-02 11:50**MOT test number** 724016012272**Result** ✓ Passed**MOT #2** 2018-01-06 10:27**MOT test number** 541128913361**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**MOT #1** 2017-01-28 09:54**MOT test number** 317781784802**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
3 February 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	3 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>PF63DKL</b>
Plate since	2019-03-29
Current registration	 <b>PF63DKL</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-01-31
Last registration	2024-01-30
Complete history	<a href="#">See info</a>



Registration #1	2014-01-31	13 mi
Registration #2	2017-01-28	46.735 mi
Registration #3	2018-01-06	67.373 mi
Registration #4	2019-01-02	88.441 mi
Registration #5	2020-01-29	106.965 mi
Registration #6	2020-01-30	106.965 mi
Registration #7	2021-02-04	122.092 mi
Registration #8	2022-05-20	151.277 mi
Registration #9	2023-05-20	151.277 mi
Registration #10	2023-05-20	151.277 mi
Registration #11	2023-05-20	151.277 mi
Registration #12	2023-05-20	151.277 mi
Registration #13	2024-01-30	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 294843K LNQ