





report date: 2024-03-29

### General information

Make	VOLVO
Model	V90 D4 INSCRIPTION
Colour	Blue
Year of manufacture	2018
Top speed	140 mph
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/10



## Internet history

### Entry 1

Date 2021-10-07

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT expiry date	2024-12-20
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	2
Total items failed	0

MOT #4	2023-11-24 13:32
MOT test number	809121976045
Result	✓ Passed
Next expiry date	2024-12-20

MOT #3	2022-12-02 10:18
MOT test number	390824026741
Result	√ Passed

MOT #2	2021-12-21 14:51
MOT test number	169167051909
Result	✓ Passed

MOT #1	2021-04-08 10:46
MOT test number	366512919787

Minor Nearside Rear Outer Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 3/10



Tax & MOT check





Expires: 20 December 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	20 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 4/10



KR18NYL

report date: 2024-03-29

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
***************************************	
***************************************	
THE STREET STREET	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 7/10



#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



KR18NYL

report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-04-27
Last registration	2023-11-24
Complete history	See info



Registration #1	2018-04-27	6 mi
Registration #2	2021-04-08	31.418 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es

More info >

CarCheck.co.uk page 9/10



KR18NYL

report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	see crash video



# Dimensions & weight

Width	1895 mm
Height	1475 mm
Length	4936 mm
Wheel base	2941 mm
Kerb weight	1696 kg
Max. allowed weight	2310 kg

## Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 10	0/10

Number of axles2Engine number2551218