





report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND SCENIC GRAND DYNAMIQUE TOMTOM VVT
Colour	Grey
Year of manufacture	2011
Top speed	115 mph
0 - 100 km/h	12.0 seconds
0 - 60 mph	12.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	162 kW / 221 HP / 109 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	178 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 2

Date 2022-08-25

Pictures 46

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2022-01-29

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



KR60OBT

report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-08-29
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	20
Total items failed	15

MOT #17	2023-08-30 09:53
MOT test number	685321457207
Result	✓ Passed
Next expiry date	2024-08-29

MOT #16	2022-08-27 10:00
MOT test number	160586152406
Result	✓ Passed

MOT #15	2022-08-27 10:00
MOT test number	308914096226
Result	X Failed

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #14		2022-02-11 10:25
MOT test i	number	491749444596
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge WORN ON OUTER ED	GE (5.2.3 (e))

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13 2022-02-08 10:43

MOT test number 217365395607

Result ★ Failed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Reversing lamp inoperative (4.6.1 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge WORN ON OUTER EDGE (5.2.3 (e))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))

Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #12 2021-03-01 14:02

MOT test number 517484505911

Result \(\sqrt{Passed} \)

Advice Nearside Play in steering rack inner joint(s)

MOT #11 2021-03-01 11:51

MOT test number 744216498241

Result × Failed

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))

Advice Nearside Play in steering rack inner joint(s)

MOT #10 2020-03-09 10:39

MOT test number 479097988124

Result

Passed

CarCheck.co.uk page 4/13



KR60OBT

report date: 2024-03-29

MOT #9 2020-03-09 09:11

MOT test number 721153142983

Result X Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8 2019-02-25 16:15

MOT test number 803016984650

Result

Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #7 2018-03-12 11:21

MOT test number 803045894719

Result \(\sqrt{Passed} \)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear fog lamp has light sources not illuminating, but not more than 50% (1.3.2b)

MOT #6 2017-01-28 12:16

MOT test number 424916355416

Result ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



report date: 2024-03-29

2016-01-29 12:12 **MOT #5** 872762448699 **MOT test number** Result ✓ Passed MOT #4 2016-01-28 12:02 **MOT** test number 453042116301 Result × Failed Offside Headlamp aim beam image obviously incorrect (1.8.A.1b) Fail **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Offside Registration plate lamp not working (1.1.C.1d) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Fail Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #3	2015-01-28 11:16
MOT test number	895218125069
Result	✓ Passed
MOT #2	2014-01-28 15:17
MOT test number	856868124051
Result	✓ Passed

Result	✓ Passed
MOT #1	2014-01-28 08:56
MOT test number	436838924067
Result	X Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	29 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

2000000	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	UK NEW
Plate since	
Current registration	NIE UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-01-31
Last registration	2023-08-30
Complete history	See info



2011-01-31	14 mi
2014-01-28	69.327 mi
2014-01-28	69.327 mi
2015-01-28	73.629 mi
2016-01-28	82.915 mi
2016-01-29	82.956 mi
2017-01-28	94.393 mi
2018-03-12	97.569 mi
2019-02-25	99.353 mi
2020-03-09	102.139 mi
	11.777 es
	11.777 44
	11.777 ea
	11,777 ea 11,777 ea 21,777 ea
	11,777 ea 11,777 ea 11,777 ea
	11,777 ea 11,777 ea 11,777 ea 11,777 ea
	2014-01-28 2015-01-28 2016-01-28 2016-01-29 2017-01-28 2018-03-12 2019-02-25 2020-03-09

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1478 mm
Height	1645 mm
Length	4560 mm
Wheel base	2770 mm
Kerb weight	1444 kg
Max. allowed weight	2074 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles 2

Engine number D089245