



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	TERRACAN CRTD CDX
Colour	Black
Year of manufacture	2007
Top speed	103 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	333 Nm at 2.000 rpm
Engine capacity	2.902 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	37.7 mpg
Consumption combined	32.8 mpg
CO2 emission	222 g/km
CO2 label	K





Internet history

Entry 2



Date	2021-10-19
Pictures	23
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-18
Pictures	23
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-29
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	15
Total items failed	13

MOT #21	2023-10-12 14:24
---------	------------------

MOT test number	726363359280
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-29
------------------	------------

- Advice** Offside Rear Inner Seat belt anchorage prescribed area is corroded but not considered excessive wheel arch (7.1.1 (a) (i))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Rear Inner Seat belt anchorage prescribed area is corroded but not considered excessive wheel arch (7.1.1 (a) (i))
- Advice** Rear brake disc inner covers missing / corroded x2
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #20** 2023-10-04 08:49**MOT test number** 797189630406**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar pin or bush excessively worn d mount bush (5.3.4 (a) (i))**Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Front Lower Suspension arm fractured (5.3.3 (b) (ii))**Fail** Nearside Rear Anti-roll bar pin or bush excessively worn d mount bush (5.3.4 (a) (i))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Rear brake disc splash guards corroded away**MOT #19** 2022-10-03 09:03**MOT test number** 112280978200**Result** ✓ Passed**MOT #18** 2021-10-30 15:42**MOT test number** 142738329382**Result** ✓ Passed**MOT #17** 2021-03-04 10:32**MOT test number** 645761358995**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #16** 2021-03-04 10:32**MOT test number** 957406088490**Result** ✗ Failed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #15** 2020-03-18 08:44**MOT test number** 141357337664**Result** ✓ Passed**MOT #14** 2019-03-19 12:14**MOT test number** 160334301429**Result** ✓ Passed**MOT #13** 2018-02-26 14:14**MOT test number** 563010089899**Result** ✓ Passed**MOT #12** 2017-03-18 08:38**MOT test number** 398377510175**Result** ✓ Passed**MOT #11** 2016-03-10 16:23**MOT test number** 819338383930**Result** ✓ Passed

**MOT #10** 2015-03-24 15:52**MOT test number** 105103385413**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #9** 2015-03-24 09:05**MOT test number** 636453685062**Result** ✗ Failed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Offside Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #8** 2014-03-07 12:51**MOT test number** 785166164037**Result** ✓ Passed**MOT #7** 2014-03-07 12:51**MOT test number** 255306664076**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #6** 2013-03-13 11:19**MOT test number** 167792473031**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-03-13 11:19**MOT test number** 785032573066**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-03-09 11:05**MOT test number** 197139562056**Result** ✓ Passed**MOT #3** 2012-03-09 11:05**MOT test number** 865279262065**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #2** 2011-03-16 11:18**MOT test number** 649485671033**Result** ✓ Passed**MOT #1** 2010-03-09 13:39**MOT test number** 812638860091**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
29 October 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	29 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-07-30
Last registration	2023-10-12
Complete history	See info



Registration #1	2007-07-30	20 mi
Registration #2	2010-03-09	10.953 mi
Registration #3	2011-03-16	16.382 mi
Registration #4	2012-03-09	21.678 mi
Registration #5	2013-03-13	32.061 mi
Registration #6	2014-03-07	37.157 mi
Registration #7	2015-03-24	42.315 mi
Registration #8	2015-03-24	42.315 mi
Registration #9	2016-03-10	46.558 mi
Registration #10	2017-03-18	51.194 mi
Registration #11	2018-02-26	57.504 mi
Registration #12	2019-03-20	61.277 mi
Registration #13	2020-03-20	65.277 mi
Registration #14	2021-03-20	69.277 mi
Registration #15	2022-03-20	73.277 mi
Registration #16	2023-03-20	77.277 mi
Registration #17	2024-03-20	81.277 mi
Registration #18	2025-03-20	85.277 mi
Registration #19	2026-03-20	89.277 mi
Registration #20	2027-03-20	93.277 mi
Registration #21	2028-03-20	97.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1860 mm
Height	1840 mm
Length	4710 mm
Wheel base	2750 mm
Kerb weight	2265 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	J3 924398