



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D3 SE LUX
Colour	Silver
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.750 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-28
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-12
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	15
Total items failed	7

MOT #15	2024-03-13 11:52
MOT test number	810194898044
Result	✓ Passed
Next expiry date	2025-03-12

MOT #14	2023-09-22 11:26
MOT test number	616698244523
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13	2022-09-23 11:20
MOT test number	503783943103
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12** 2022-09-13 14:29**MOT test number** 299528813089**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Rear (5.3.4 (a) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn Rear (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2021-09-08 08:56**MOT test number** 569250897380**Result** ✓ Passed**MOT #10** 2020-09-17 14:18**MOT test number** 642019478067**Result** ✓ Passed**MOT #9** 2020-09-17 14:18**MOT test number** 359096366816**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #8** 2019-09-13 14:09**MOT test number** 711462358371**Result** ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Front tyre slightly worn on edges
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Rear Brake pad(s) wearing thin pads around 4mm remaining (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Front Windscreen wiper blade defective were dirty cleaned up but still slightly smearing (3.4 (b) (i))

**MOT #7** 2018-09-19 10:01**MOT test number** 833312162827**Result** ✓ Passed**MOT #6** 2017-09-08 10:49**MOT test number** 201316608384**Result** ✓ Passed

- Advice** Brake pedal anti slip pad worn

**MOT #5** 2016-09-19 15:55**MOT test number** 354044192802**Result** ✓ Passed**MOT #4** 2016-06-13 15:43**MOT test number** 480839980955**Result** ✓ Passed



MOT #3	2016-06-13 13:33
MOT test number	173861028499
Result	✗ Failed
Fail	Nearside Front Tyre has ply or cords exposed on both tyre edges (4.1.D.1b)
Fail	Offside Front Tyre has ply or cords exposed on inner tyre edge (4.1.D.1b)

MOT #2	2015-06-16 16:27
MOT test number	857317165106
Result	✓ Passed

MOT #1	2014-12-16 11:49
MOT test number	435610454389
Result	✓ Passed
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
12 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	12 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-29
Current registration	 
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-12-15
Last registration	2024-03-13
Complete history	<a href="#">See info</a>



Registration #1	2011-12-15	9 mi
Registration #2	2014-12-16	32.554 mi
Registration #3	2015-06-16	41.695 mi
Registration #4	2016-06-13	55.408 mi
Registration #5	2016-06-13	55.408 mi
Registration #6	2016-09-19	56.930 mi
Registration #7	2017-09-08	63.082 mi
Registration #8	2018-09-19	68.349 mi
Registration #9	2019-09-13	71.056 mi
Registration #10	2020-09-13	75.377 mi
Registration #11	2021-09-13	79.700 mi
Registration #12	2022-09-13	84.023 mi
Registration #13	2023-09-13	88.346 mi
Registration #14	2024-03-13	92.669 mi
Registration #15	2024-03-13	92.669 mi
Registration #16	2024-03-13	92.669 mi
Registration #17	2024-03-13	92.669 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1561 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	1026084
---------------	---------