



General information	report date: 2024-03-28

Make	DODGE (USA)
Model	AVENGER SE
Colour	Silver
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	310 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.4 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	170 g/km
CO2 label	Н



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/15



RJ570NN

report date: 2024-03-28

MOT history

MOT expiry date	2022-01-11
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	49
Total items failed	12

MOT #15	2021-01-12 14:00
MOT test number	544256840684
Result	✓ Passed
Next expiry date	2022-01-11
Advice Offside Rear Brake hose has slight corrosion to ferrule both ends (1.1.12 (f) (i))	

MOT #14 2020-02-20 16:19

MOT test number 684932546975

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement play to rear wishbone bush (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement play to rear wishbone bush (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13 2020-02-19 11:12

MOT test number 450158423279

Result × Failed

Fail Nearside Front Lower Suspension arm ball joint excessively worn excessive play to lower ball joint (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement play to rear wishbone bush (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement play to rear wishbone bush (5.3.4 (a) (i))

CarCheck.co.uk page 3/15



Result

RJ57ONN report date: 2024-03-28

✓ Passed

MOT #12 2019-02-07 16:31

MOT test number 118626546096

Result
✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #11 2018-02-10 12:44

MOT test number 248195797819

Result ✓ Passed

MOT #10 2017-01-28 12:23

MOT test number 351488879052

Result
✓ Passed

MOT #9 2016-02-05 08:59

MOT test number 942147812053

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Offside Rear Outer Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Brake hose has slight corrosion to ferrules front hose (3.6.B.4e)

Advice Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)

Advice Engine oil leak covering steering rack offside & power steering hoses

Advice Offside Front tyre . cuts in tyre treads & outer wall

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Brake hose has slight corrosion to ferrules front hose (3.6.B.4e)

CarCheck.co.uk page 4/15



report date: 2024-03-28

2015-02-17 07:33

MOT #8 MOT test number 328598745085 Result ✓ Passed Notice Slight brake bind nearside front Notice Under-trays fitted obscuring some underside components Advice Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e) Notice Play in steering rack inner joint(s) Notice Front and rear tyres worn more inner edges Notice Handbrake warning light flashes when handbrake is on Advice Rear Brake pad(s) wearing thin (3.5.1g) Notice Engine covers fitted obscuring some components in the engine bay Notice Oil leak

CarCheck.co.uk page 5/15



RJ570NN

report date: 2024-03-28

MOT #7 2015-02-10 15:09 **MOT** test number 375361945065 Result × Failed Fail Nearside Outer Front Track rod end ball joint has excessive play (2.2.B.1f) Notice Slight brake bind nearside front Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Notice Under-trays fitted obscuring some underside components **Advice** Rear Brake pad(s) wearing thin (3.5.1g) Notice Play in steering rack inner joint(s) Notice Front and rear tyres worn more inner edges Fail Offside Front position lamp(s) not working (1.1.A.3b) Fail Offside Outer Front Track rod end ball joint has excessive play (2.2.B.1f) **Notice** Handbrake warning light flashes when handbrake is on Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b) Notice Engine covers fitted obscuring some components in the engine bay Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e) **Advice Notice** Oil leak Fail Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #6	2014-02-04 09:24
MOT test number	378825134036
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f)	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 6/15



RJ570NN

report date: 2024-03-28

MOT test number

Result

Advice

Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

Advice

Rear Brake pad(s) wearing thin (3.5.1g)

Pass with rectification

Offside Front position lamp(s) not working (1.1.A.3b)

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4

MOT test number

Result

Advice

Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

MOT #3 2013-01-15 10:56 629775913098 **MOT** test number Result × Failed **Fail** Offside Front Driver's door cannot be opened from inside the vehicle (6.2.B.1b) **Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g) Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Offside Front Driver's door cannot be opened from outside the vehicle (6.2.B.1b) **Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 7/15



MOT #2 2012-01-19 11:35

MOT test number 735849512039

Result
✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2010-11-25 10:32

MOT test number 174219020376

Result ✓ Passed

CarCheck.co.uk page 8/15



Tax & MOT check

Tax expired: 31 August 2021



Expired: 11 January 2022 X MOT

Tax status	Expired at 31 August 2021
Days left	971 days too late
MOT expiry date	11 January 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this DODGE (USA). See if, where and when this DODGE (USA) had damage and the car repair costs. We also check if this DODGE (USA) was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category


Type

Damage 2

Date

Category

Type



Extra DODGE (USA) salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this DODGE (USA) in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

Owner history	
For how long did the current and previous owner(s) have this DODGE (USA)? How many DODGE (USA) have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this DODGE (USA) had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	ZIS UK
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this DODGE (USA) is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this DODGE (USA) has been settled.

If not, and you buy this DODGE (USA) then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this DODGE (USA) is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-12-04
Last registration	2021-01-12
Complete history	See info



Registration #1	2007-12-04	24 mi
Registration #2	2010-11-25	37.149 mi
Registration #3	2012-01-19	53.660 mi
Registration #4	2013-01-15	67.259 mi
Registration #5	2013-02-04	68.135 mi
Registration #6	2014-02-04	82.253 mi
Registration #7	2015-02-10	96.288 mi
Registration #8	2015-02-17	96.508 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		11.777 mi
Registration #16		10.777 au

More info >

CarCheck.co.uk page 14/15



Dimensions &	k weig	ht
--------------	--------	----

Width	1843 mm
Height	1497 mm
Length	4850 mm
Wheel base	2765 mm
Kerb weight	1635 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	DIESEL

CarCheck.co.uk page 15/15