





report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 DSTYLE PLUS
Colour	Blue
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-07-24

Pictures 52

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-23
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #8	2023-07-18 16:54
MOT test number	750327226891
Result	✓ Passed
Next expiry date	2024-07-23
Advice Front Upper Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #7	20	22-07-22 14:51
MOT test	number	890776844474
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively both (1.1.14 (a) (i))	
Advice Slight exhaust blow from behind front flexible pipe plus support bracket partially broken		ken
Advice	Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside front tyre has inner sidewall damage and cut to cords not deep enough to s	show.

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2022-07-22 11:19 215174145992 **MOT** test number Result × Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside front tyre has inner sidewall damage and cut to cords not deep enough to show. **Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i)) Advice Engine oil level low **Advice** Slight exhaust blow from behind front flexible pipe plus support bracket partially broken Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

 MOT #5
 2021-07-24 11:00

 MOT test number
 147463440436

 Result
 ✓ Passed

 MOT #4
 2020-08-05 10:41

 MOT test number
 889700781789

 Result
 ✓ Passed

 Advice
 Rear tyres cracked

MOT #3

MOT test number

770825460780

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm on edge (5.2.3 (e))

MOT #2

MOT test number

671971174335

Result

Advice Offside Front Nail in tyre

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2017-08-16 08:23
MOT test number 896432283155

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	23 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		ROEN
THE PARTY OF THE P		

	More info	>
Plate changes See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-09-03
Last registration	2023-07-18
Complete history	See info



Registration #1	2014-09-03	20 mi
Registration #2	2017-08-16	7.449 mi
Registration #3	2018-08-15	11.304 mi
Registration #4	2019-08-24	16.788 mi
Registration #5	2020-08-05	21.331 mi
Registration #6		
negionation # o		
Registration #7		11.777 es
-		11.777 es
Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1147 kg
Max. allowed weight	1554 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCA2103961

CarCheck.co.uk page 12/12