



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK320 AVANTGARDE
Colour	Black
Year of manufacture	2004
Top speed	150 mph
0 - 60 mph	8.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	218 BHP
Max. torque	310 Nm at 3.000 rpm
Engine capacity	3.199 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.0 mpg
Consumption extra urban	36.7 mpg
Consumption combined	27.2 mpg
CO2 emission	262 g/km
CO2 label	M





Internet history

Entry 2

Date	2022-01-26
Pictures	9
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-09-13
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	83
Total items failed	11

MOT #23 2023-09-14 11:49

MOT test number 814575316419

Result ✓ Passed

Next expiry date 2024-09-13

- Advice** Underbody tray fitted
- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #22 2022-07-21 10:51

MOT test number 124226464036

Result ✓ Passed

- Advice** Anti-roll bar linkage pin or bush worn but not resulting in excessive movement n/s/r & o/s/r (5.3.4 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material n/s/r & o/s/r leads to hoses (1.1.11 (c))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play rear (5.3.4 (a) (i))
- Advice** Coil spring corroded n/s/r & o/s/r (5.3.1 (b) (i))



MOT #21

2021-07-08 11:53

MOT test number

816446792090

Result

✓ Passed

- Advice

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice

Front Child Seat fitted not allowing full inspection of adult belt
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice

Exhaust heat shield insecure
- Advice

Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice

Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor

Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Hand brake pedal rubber missing
- Advice

Rear Anti-roll bar linkage ball joint has slight play both (5.3.4 (a) (i))
- Advice

Covers fitted under vehicle obscuring some components

**MOT #20**

2020-06-19 11:58

MOT test number

337401544810

Result

✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Exhaust mounting defective (6.1.2 (a))**Advice** Nearside park brake efficiency low**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Brake fluid warning lamp illuminated (1.1.10 (f))**Advice** Engine covers and undertrays fitted**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Track rod end ball joint has slight play Strong Advise (2.1.3 (b) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #19**

2019-08-01 09:58

MOT test number

430647422998

Result

✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Minor** Brake fluid warning lamp illuminated (1.1.10 (f))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both front discs (1.1.14 (a) (ii))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Undertrays fitted

**MOT #18**

2018-06-26 09:19

MOT test number

555148409469

Result

✓ Passed

- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Lazy park brake
- Advice** Front brake discs worn
- Advice** 1 of front exhaust brackets broken loose
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #17

2017-06-21 16:03

MOT test number

888060339847

Result

✓ Passed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Crack in windscreen

MOT #16

2017-06-20 09:21

MOT test number

234355322027

Result

✗ Failed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Crack in windscreen
- Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)
- Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

**MOT #15** 2016-06-30 08:39**MOT test number** 564588882042**Result** ✓ Passed**Advice** Nearside Front brake pipe corroded**Advice** 1 of front exhaust mounts broken loose**Advice** Front brake discs worn**MOT #14** 2015-07-01 16:45**MOT test number** 577572585128**Result** ✓ Passed**Notice** Front brake discs worn.**Notice** Grab on both front brakes.**Notice** N/s front brake pipe corroded.**MOT #13** 2015-06-25 12:56**MOT test number** 166156675175**Result** ✗ Failed**Notice** Both front exhaust brackets corroded and broken loose.**Notice** 1 of rear exhaust brackets corroded and broken loose.**Notice** N/s front brake pipe corroded.**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Grab on both front brakes.**Notice** Front brake discs worn.**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Offside Front Subframe mounting prescribed area is excessively corroded (2.4.A.3)

**MOT #12** 2014-07-15 10:16**MOT test number** 715906594109**Result** ✓ Passed**Notice** Front brake discs slightly worn**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #11** 2014-07-07 11:57**MOT test number** 497838684186**Result** ✗ Failed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Notice** Front brake discs slightly worn**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #10** 2013-07-12 17:58**MOT test number** 597183493179**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2012-11-28 15:17**MOT test number** 269883132390**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2012-11-28 12:26**MOT test number** 775233032361**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2011-11-19 13:03**MOT test number** 677383721392**Result** ✓ Passed**MOT #6** 2010-10-26 10:43**MOT test number** 861769790269**Result** ✓ Passed**MOT #5** 2009-11-23 15:19**MOT test number** 142947929315**Result** ✓ Passed**MOT #4** 2009-11-16 16:49**MOT test number** 842340029354**Result** ✗ Failed**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Front coil spring fractured (2.4.C.1a)**MOT #3** 2008-11-17 16:41**MOT test number** 292092428350**Result** ✓ Passed



MOT #2	2007-11-22 10:26
MOT test number	121976127334
Result	✓ Passed
MOT #1	2006-11-23 11:56
MOT test number	464417626468
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
13 September 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	13 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-01-06
Last registration	2023-09-14
Complete history	See info



Registration #1	2004-01-06	19 mi
Registration #2	2006-11-23	27.100 mi
Registration #3	2007-11-22	33.359 mi
Registration #4	2008-11-17	38.898 mi
Registration #5	2009-11-16	45.028 mi
Registration #6	2009-11-23	45.144 mi
Registration #7	2010-10-26	50.734 mi
Registration #8	2011-11-19	56.552 mi
Registration #9	2012-11-28	62.143 mi
Registration #10	2012-11-28	62.143 mi
Registration #11	2013-07-12	65.037 mi
Registration #12	2014-07-07	70.940 mi
Registration #13	2014-07-15	71.081 mi
Registration #14	2015-05-20	75.377 mi
Registration #15	2015-05-20	75.377 mi
Registration #16	2015-05-20	75.377 mi
Registration #17	2015-05-20	75.377 mi
Registration #18	2015-05-20	75.377 mi
Registration #19	2015-05-20	75.377 mi
Registration #20	2015-05-20	75.377 mi
Registration #21	2015-05-20	75.377 mi
Registration #22	2015-05-20	75.377 mi
Registration #23	2015-05-20	75.377 mi
Registration #24	2015-05-20	75.377 mi
Registration #25	2015-05-20	75.377 mi
Registration #26	2015-05-20	75.377 mi

More info >



Dimensions & weight

Width	1740 mm
Height	1413 mm
Length	4643 mm
Wheel base	2690 mm
Kerb weight	1730 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	5
Number of axles	2
Engine number	11295531843194