





report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Silver
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	181 g/km
CO2 label	I



CarCheck.co.uk page 1/15



report date: 2024-03-29


Internet history

Entry 1

Date 2022-06-22

Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-09-08
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	41
Total items failed	4

MOT #20		2023-09-05 11:49
MOT test	number	115436797021
Result		✓ Passed
Next expi	ry date	2024-09-08
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Power steering component has slight seepage from a component steering	rack (2.1.5 (a))

MOT #19	2022-09-09 14:06
MOT test number	173964766757
Result	✓ Passed

Result		✓ Passed
MOT #18		2021-11-02 08:53
MOT test	number	132066463869
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Macpherson strut mounting damaged but not seriously weakened and knocking from front suspension (5.3.3 (b) (i))		g from front
Advice	General corrision on suspension parts	
Advice	Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Rear Bumper mountings corroded but not likely to become detached (6.1.4 (a)) (i))
Advice	Front bumper cover damaged	

CarCheck.co.uk page 3/15



suspension (5.3.3 (b) (i))

EY57LFM

report date: 2024-03-29

MOT #17 2021-10-28 11:12 369482475026 **MOT** test number Result **★** Failed **Advice** Rear Bumper mountings corroded but not likely to become detached (6.1.4 (a) (i)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **MAJOR** Offside Front Headlamp aim too low (4.1.2 (a)) Advice General corrision on suspension parts Fuel cap/sealing device missing (6.1.3 (b) (i)) **MAJOR MAJOR** Offside Front Position lamp not working side light (4.2.1 (a) (ii)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Macpherson strut mounting damaged but not seriously weakened and knocking from front

MOT #16		2020-08-18 12:06
MOT test number		360742713137
Result		✓ Passed
Advice Coolant I	leak	
Advice Rear Tyr	re worn close to legal limit/worn on edge both sides (5.2.3 (e))	

CarCheck.co.uk page 4/15



Passed

MOT #15 2020-08-14 15:18

769831206381 **MOT** test number

Result × Failed

MAJOR Offside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))

MAJOR Offside Rear Direction indicator incorrect colour (4.4.3 (a))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Coolant leak

Nearside Rear Direction indicator incorrect colour (4.4.3 (a)) **MAJOR**

Advice Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #14 2019-08-17 16:03

MOT test number 517516688829

Result

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13 2019-08-17 16:03

MOT test number 466964072143

Result × Failed

Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #12	2018-08-17 10:39	
MOT test number	289358515192	
Result	✓ Passed	
Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm. (5.2.3 (e))		
Advice Nearside Rear Direction indicator slightly discoloured White. (4.4.3 (a))		
Minor Offside Obligatory mirror slightly loose (3.3 (b) (i))		
Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated Slight leak of cv grease. (6.1.7 (g) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm. (5.2.3 (e))		
Advice Fluid leak, but not excessive Coolant. (8.4.1 (a) (i))		
Minor Offside Rear Tyre obviously under inflated Cracking within tread. (5.2.3 (h) (i))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		

MOT #11	2017-08-04 07:51
MOT test number	545299708799
Result	✓ Passed
MOT #10	2016-08-05 08:57
MOT test number	148817859382
Result	✓ Passed
MOT #9	2015-08-07 12:28
MOT test number	139429415240
Result	✓ Passed

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #8

MOT test number

545353624281

Result

Notice Nearside front tyre worn inner edge

Notice Offside front tyre worn low/worn edges and perished

MOT #7

MOT test number

Result

MOT #6

2013-08-17 12:20

729909523220

✓ Passed

MOT test number

Result

Fail Nearside Rear Stop lamp not working (1.2.1b)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Tested wet front brake discs lipped

Fail Offside Rear Stop lamp not working (1.2.1b)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #5

MOT test number

957350692222

Result

Notice Wiper starting to smear

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #4	2012-10-16 14:21	
MOT test number	257470292273	
Result	X Failed	
Notice Wiper starting to smear		
Pass with rectification Offside Stop lamp not working (1.2.1b)		

Pass with rectification	Offside Stop lamp not working (1.2.1b)	
MOT #3		2011-10-17 12:23
MOT test number		845700691293
Result		✓ Passed
MOT #2		2010-10-11 17:01
MOT test number		181504180206
Result		✓ Passed
MOT #1		2010-08-17 13:18
MOT test number		371059620487
Result		✓ Passed

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	8 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	AIZ SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-18
Last registration	2023-09-05
Complete history	See info



Registration #1	2007-09-18	29 mi
Registration #2	2010-08-17	21.262 mi
Registration #3	2010-10-11	22.366 mi
Registration #4	2011-10-17	25.908 mi
Registration #5	2012-10-16	36.428 mi
Registration #6	2013-08-16	47.555 mi
Registration #7	2013-08-17	47.555 mi
Registration #8	2014-08-11	54.587 mi
Registration #9	2015-08-07	63.286 mi
Registration #10	2016-08-05	69.668 mi
Registration #11	2017-08-04	75.962 mi
Registration #12		11.117 es
Registration #13		11.777 es
Registration #14		11.117 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.117 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11,777 66

More info >

CarCheck.co.uk page 14/15



Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/1

Number of axles 2

Engine number 7E54776