



SJ59UYM

report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE PLUS
Colour	Silver
Year of manufacture	-
Top speed	103 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	95 BHP
Max. torque	128 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	43.5 mpg



LABEL UNKNOWN



MOT history

MOT #12	2020-09-14 13:37
MOT test number	426628654373
Result	✓ Passed
Next expiry date	2021-09-26
Advice	Vehicles internal headlight adjuster altered to recheck lights

MOT #11	2019-09-27 12:13
MOT test number	493961597207
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #10	2018-07-27 08:25
MOT test number	422385309411
Result	✓ Passed
Minor	Front Windscreen damaged but not adversely affecting driver's view zone b (3.2 (a) (i))
Minor	Offside Front Obligatory mirror slightly damaged mirror housing. (3.3 (b) (i))

MOT #9	2018-07-27 08:25
MOT test number	638717261584
Result	✗ Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Minor	Front Windscreen damaged but not adversely affecting driver's view zone b (3.2 (a) (i))
Minor	Offside Front Obligatory mirror slightly damaged mirror housing. (3.3 (b) (i))

**MOT #8** 2017-08-01 12:14**MOT test number** 494092599252**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #7** 2016-08-18 11:25**MOT test number** 287534590339**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Front Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Engine cover fitted.**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' Chip in windscreen.
(8.3.1d)**MOT #6** 2015-08-18 00:00**MOT test number** 279839232052**Result** ✓ Passed**MOT #5** 2015-07-27 15:13**MOT test number** 318388705245**Result** ✓ Passed

**MOT #4** 2015-07-27 11:57**MOT test number** 217178505259**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2014-07-25 16:47**MOT test number** 667696204217**Result** ✓ Passed**Notice** Vehicle's internal headlight adjuster altered to recheck lights**MOT #2** 2013-08-13 11:50**MOT test number** 295205823275**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-08-23 16:27**MOT test number** 349666932248**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-09-28
Last registration	2020-09-14
Complete history	See info



Registration #1	2009-09-28	12 mi
Registration #2	2012-08-23	2.118 mi
Registration #3	2013-08-13	9.620 mi
Registration #4	2014-07-25	18.112 mi
Registration #5	2015-07-27	26.996 mi
Registration #6	2015-07-27	26.996 mi
Registration #7	2015-08-18	27.588 mi
Registration #8	2015-08-18	27.588 mi
Registration #9	2015-08-18	27.588 mi
Registration #10	2015-08-18	27.588 mi
Registration #11	2015-08-18	27.588 mi
Registration #12	2015-08-18	27.588 mi
Registration #13	2015-08-18	27.588 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1922 mm
Height	1481 mm
Length	3958 mm
Wheel base	2489 mm
Kerb weight	966 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9J10615