



TOYOTA



report date: 2024-03-28

General information

|                     |                       |
|---------------------|-----------------------|
| Make                | TOYOTA                |
| Model               | AVENSIS VALVEMATIC TR |
| Colour              | Grey                  |
| Year of manufacture | 2011                  |
| Top speed           | 124 mph               |
| 0 - 60 mph          | 9.7 seconds           |
| Gearbox             | 6 speed Manual        |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 147 BHP             |
| Max. torque             | 180 Nm at 4.000 rpm |
| Engine capacity         | 1.798 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 32.8 mpg            |
| Consumption extra urban | 52.3 mpg            |
| Consumption combined    | 42.8 mpg            |
| CO2 emission            | 155 g/km            |
| CO2 label               | G                   |





## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2021-10-18 |
| MOT pass rate      | 88 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 1          |
| Total advice items | 10         |
| Total items failed | 2          |

|                  |                  |
|------------------|------------------|
| MOT #8           | 2020-09-21 09:54 |
| MOT test number  | 448363251790     |
| Result           | ✓ Passed         |
| Next expiry date | 2021-10-18       |

|                 |   |
|-----------------|---|
| MOT #7          | 2019-03-20 09:05  |
| MOT test number | 765217284057  |
| Result          | ✓ Passed  |
| Minor           | Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) |

|                 |   |
|-----------------|---|
| MOT #6          | 2019-03-19 09:06  |
| MOT test number | 477190336521  |
| Result          | ✗ Failed  |
| Fail            | Offside Windscreen washer provides insufficient washer liquid (3.5 (a))   |
| Fail            | Front Brake pad(s) less than 1.5 mm thick bothsides (1.1.13 (a) (ii))   |
| Minor           | Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) |

**MOT #5** 2018-04-16 14:51**MOT test number** 660601690967**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside washer jet inoperative**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2017-04-18 14:39**MOT test number** 127996208361**Result** ✓ Passed**MOT #3** 2016-04-18 12:53**MOT test number** 302105000371**Result** ✓ Passed**MOT #2** 2015-03-27 13:46**MOT test number** 396896785001**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Front wipers smear**MOT #1** 2014-04-19 09:40**MOT test number** 295599804421**Result** ✓ Passed**Notice** Items removed from driver's view prior to test



Tax & MOT check

X

Untaxed

Tax expired:  
14 April 2021

X

MOT

Expired:  
18 October 2021

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 14 April 2021        |
| Days left        | 1112 days too late              |
| MOT expiry date  | 18 October 2021                 |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 48         |
| Band                                    | G          |
| Single payment (12 months)              | £ 240,00,- |
| Single six month payment                | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | *****      |
| Plate since          | 2019-09-29 |
| Current registration | *****      |
| Plate since          | 2019-09-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >





Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 9                        |
| First mileage registration | 2011-02-01               |
| Last registration          | 2020-09-21               |
| Complete history           | <a href="#">See info</a> |



|                 |            |           |
|-----------------|------------|-----------|
| Registration #1 | 2011-02-01 | 16 mi     |
| Registration #2 | 2014-04-19 | 29.853 mi |
| Registration #3 | 2015-03-27 | 40.138 mi |
| Registration #4 | 2016-04-18 | 50.174 mi |
| Registration #5 | 2017-04-18 | 59.990 mi |
| Registration #6 | 2018-05-29 | 69.777 mi |
| Registration #7 | 2019-05-29 | 79.577 mi |
| Registration #8 | 2020-05-29 | 89.377 mi |
| Registration #9 | 2020-09-21 | 99.177 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 90%                             |
| Children       | 86%                             |
| Pedestrian     | 53%                             |
| Safety systems | 86%                             |
| Overall rating | 81%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1810 mm |
| Height              | 1480 mm |
| Length              | 4780 mm |
| Wheel base          | 2700 mm |
| Kerb weight         | 1450 kg |
| Max. allowed weight | 2000 kg |

Additional information

|                 |                       |
|-----------------|-----------------------|
| Fuel delivery   | Multi-Point Injection |
| Number of doors | 5                     |
| Number of seats | 5                     |
| Number of axles | 2                     |

**Engine number**

2ZRU413134