





report date: 2024-03-29

### General information

Make	MERCEDES
Model	SL SL350
Colour	Blue
Year of manufacture	2003
Top speed	155 mph
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	245 BHP
Max. torque	350 Nm at 3.000 rpm
Engine capacity	3.724 cc
Cylinders	6
Fuel type	Petrol
Consumption city	16.1 mpg
Consumption extra urban	34.0 mpg
Consumption combined	24.1 mpg
CO2 emission	281 g/km
CO2 label	M



CarCheck.co.uk page 1/14



## Internet history

#### Entry 2

Listing price

Date	2021-11-08
Pictures	1

View report



source: autotrader.co.uk

#### Entry 1

Date	2021-09-06	
Pictures	13	
Listing price	<u>View report</u>	









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-12-10
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	26
Total items failed	6

MOT #23	2023-12-11 12:27
MOT test number	138812567698
Result	✓ Passed
Next expiry date	2024-12-10

MOT #22	2023-10-25 10:00
MOT test number	847429313009
Result	<b>X</b> Failed
Fail Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))	

MOT #21	2022-11-08 13:23
MOT test number	273555630383
Result	✓ Passed
MOT #20	2022-11-08 11:14
MOT test number	222325109745
Result	<b>X</b> Failed
Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))	

MOT #19	2021-11-24 13:35
MOT test number	109020327369
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/14



Result

LG53LVL report date: 2024-03-29

✓ Passed

**MOT #18** 2021-01-20 15:53

**MOT test number** 339469614230

Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #17** 2020-01-31 16:57

**MOT test number** 766812233499

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #16** 2020-01-15 14:56

MOT test number 443904484026

Result × Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Rear fog lamp not working (4.5.1 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/14



MOT #15 2019-01-22 17:22

**MOT test number** 128375512109

**MOT #14** 2019-01-22 11:05

**MOT test number** 276380191720

Result × Failed

**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure inner wall (5.2.3 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13 2019-01-15 09:31

**MOT test number** 611136053372

Result X Failed

**Advice** NSF tyre close to limit

**Fail** Offside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #12** 2018-01-11 09:42

MOT test number 295678132630

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Slight perishing to the tread on the front tyres

**MOT #11** 2017-01-04 15:01

**MOT test number** 540606727409

**Advice** Nearside Front tyre tread perished

**Advice** Front wipers slightly smearing screen

CarCheck.co.uk page 5/14



 MOT #10
 2016-01-15 10:59

 MOT test number
 359866370988

 Result
 ✓ Passed

 Advice
 N/s/r tyre worn to wear bar 2mm

MOT test number

Result

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Both rear tyres perishing/cracking

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #7
 2013-02-14 17:29

 MOT test number
 596355843026

 Result
 ✓ Passed

 MOT #6
 2012-04-13 10:10

 MOT test number
 575344602112

 Result
 X Failed

 Pass with rectification
 Nearside Headlamp aim too low (1.8)

CarCheck.co.uk page 6/14



MOT #5	2012-04-13 10:10
MOT test number	936074802166
Result	<b>✓</b> Passed
MOT #4	2010-05-05 18:46
MOT test number	211985520412
Result	<b>✓</b> Passed
MOT #3	2009-03-26 16:16
MOT test number	714155889086
Result	✓ Passed
MOT #2	2008-03-20 19:54
MOT test number	410530888032
Result	✓ Passed
MOT #1	2007-02-05 13:43
MOT test number	992396537023
Result	✓ Passed

CarCheck.co.uk page 7/14



### Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	10 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14




### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



#### Extra MERCEDES salvage check



Category

**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	AIS UK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 11/14



#### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-12-23
Last registration	2023-12-11
Complete history	See info



Registration #1	2003-12-23	7 mi
Registration #2	2007-02-05	173 mi
Registration #3	2008-03-20	3.475 mi
Registration #4	2009-03-26	6.638 mi
Registration #5	2010-05-05	9.349 mi
Registration #6	2012-04-13	14.297 mi
Registration #7	2013-02-14	16.634 mi
Registration #8	2014-01-13	19.838 mi
Registration #9	2015-01-16	27.134 mi
Registration #10	2016-01-15	31.255 mi
Registration #11	2017-01-04	33.954 mi
Registration #12	2018-01-11	37.346 mi
Registration #13	2019-01-15	39.358 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		71.777 es
Registration #25		11.777 es



		_		
I ) I m	ension	c l	MOIG	nt.
	CHSIUH	3 W	welu	III.

Width	1982 mm
Height	1288 mm
Length	4499 mm
Wheel base	2515 mm
Kerb weight	1755 kg
Max. allowed weight	2050 kg

## Additional information

Fuel tank capacity	80 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11297331613931

CarCheck.co.uk page 14/14