





report date: 2024-03-28

General information

Make	AUDI
Model	A5 TFSI SE
Colour	Black
Year of manufacture	2008
Top speed	143 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	230 Nm at 4.500 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.8 mpg
CO2 emission	169 g/km
CO2 label	Н



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 3

Date 2023-02-10

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2023-01-11
------	------------


Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-06-14

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

MOT expiry date	2024-12-28
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	37
Total items failed	14

MOT #21	2023-12-29 14:15
MOT test number	608837246529
Result	✓ Passed
Next expiry date	2024-12-28
Advice Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	

MOT #20		2022-11-02 13:06
MOT test	number	965101975832
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))		uter sidewall (5.2.3
Advice	Fluid leak, but not excessive Coolant leak (8.4.1 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #19 2022-11-01 16:59

MOT test number 417570527268

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt Forward arm (5.3.4 (b) (ii))

Advice Fluid leak, but not excessive Coolant leak (8.4.1 (a) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3

(d) (i))

MOT #18 2021-11-19 09:51

MOT test number 299372148254

Result \(\sqrt{Passed} \)

MOT #17 2021-11-18 16:22

MOT test number 186087388348

Result X Failed

DANGEROUS Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure inner side wall (5.2.3 (d) (ii))

MOT #16 2020-11-13 17:45

MOT test number 854429467393

Result \(\sqrt{Passed} \)

Advice Front Tyre worn close to legal limit/worn on edge Nearside / Offside (5.2.3 (e))

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #15 2020-11-13 16:04

MOT test number 743445538908

Result X Failed

MAJOR Front Windscreen wiper does not clear the windscreen effectively Nearside / Offside (3.4 (b) (ii))

Advice Front Tyre worn close to legal limit/worn on edge Nearside / Offside (5.2.3 (e))

MAJOR Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #14 2019-06-08 09:50

MOT test number 325707155009

Result ✓ Passed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2019-06-06 15:48

MOT test number 495698845541

Result × Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #12 2018-05-10 11:57

MOT test number 377340658409

Result
✓ Passed

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #11 2018-05-08 10:32

MOT test number 687244122727

Result X Failed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened and o/s/f lipped (3.5.1i)

Fail Nearside Front Headlamp aim too high and o/s/f (1.8)

Fail Offside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Central Front registration plate faded but not likely to be misread (6.3.1d)

Fail Nearside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #10 2017-05-13 16:14

MOT test number 301906123098

Result ✓ Passed

MOT #9 2017-05-13 10:31

MOT test number 118800625690

Result × Failed

Fail Offside Rear Shock absorber has a serious fluid leak and n/s/r reduced damping effect (2.7.3)

MOT #8 2016-04-23 16:25

MOT test number 607525347643

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear and o/s/r nail on tyre

Advice Nearside Front Inner Suspension arm rubber mounting deteriorated but not resulting in excessive movement rear and (o/s/f) rear (2.4.G.2)

Advice Engien mangment light on

Advice Nearside Front Inner Suspension arm rubber mounting deteriorated but not resulting in excessive

movement front and (o/s/f) inner (2.4.G.2)

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #7 2016-04-23 10:18

MOT test number 678172761870

Result X Failed

Advice Nearside Front Inner Suspension arm rubber mounting deteriorated but not resulting in excessive movement rear and (o/s/f) rear (2.4.G.2)

Advice Nearside Rear and o/s/r nail on tyre

Fail Nearside Front Brake pad(s) less than 1.5 mm thick and o/s/f (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Inner Suspension arm rubber mounting deteriorated but not resulting in excessive movement front and (o/s/f) inner (2.4.G.2)

Advice Engien mangment light on

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick and o/s/r (3.5.1g)

Fail Nearside Front brake disc modified and seriously weakened and o/s/f (3.5.1n)

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick and o/s/r (3.5.1g)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #6 2015-05-08 12:42

MOT test number 699878225121

Result ✓ Passed

MOT #5 2014-05-17 14:04

MOT test number 255177834419

Result ✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #4	2014-05-17 14:04
MOT test number	248297534123
Result	★ Failed
Pass with rectification	Offside Front Headlamp aim too far to the right (1.8)
Pass with rectification	Nearside Front Headlamp aim too high and too far to the left. (1.8)
Pass with rectification	Offside Front Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)

MOT #3	2013-05-16 11:55
MOT test number	289316033164
Result	✓ Passed
MOT #2	2012-04-19 14:27

MOT #2	2012-04-19 14.27
MOT test number	827080812101
Result	✓ Passed

MOT #	1 203	12-04-12 10:04
MOT te	est number	138563002170
Result		X Failed
Fail	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.	1.D.1b)
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	

CarCheck.co.uk page 8/15



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	28 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



HF08EEG report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

More info >

Owner history		
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report		ve?

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	NK MK	
Plate since		

CarCheck.co.uk page 12/15



HF08EEG report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2008-06-24
Last registration	2023-12-29
Complete history	See info



Registration #1	2008-06-24	17 mi
Registration #2	2012-04-12	28.762 mi
Registration #3	2012-04-19	28.762 mi
Registration #4	2013-05-16	38.804 mi
Registration #5	2014-05-17	45.070 mi
Registration #6	2015-05-08	51.982 mi
Registration #7	2016-04-23	60.315 mi
Registration #8	2016-04-23	60.315 mi
Registration #9	2017-05-13	71.834 mi
Registration #10	2017-05-13	71.834 mi
Registration #11	2018-05-08	79.587 mi
Registration #12	2018-05-10	79.587 mi
Registration #13		11,117 es
Registration #14		11.117 ea
Registration #15		11,117 es
Registration #16		11.117 ea
Registration #17		11,117 es
Registration #18		11.117 ea
Registration #19		11,117 es
Registration #20		11.117 ea
Registration #21		11.177 mi
Registration #22		11.777 44
Registration #23		11.777 66
Registration #24		71,777 ea

More info >



HF08EEG
report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1427 mm
Length	4703 mm
Wheel base	2808 mm
Kerb weight	1410 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	65 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page	15/15

Number of axles2Engine numberCAB 019230