



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Grey
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-05-30
Pictures	22
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2025-03-15
<b>MOT pass rate</b>	92 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	25
<b>Total items failed</b>	0

<b>MOT #12</b>	2024-03-16 11:00
<b>MOT test number</b>	724434400468
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-03-15
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Nearside Front Coil spring corroded (5.3.1 (b) (i))

<b>MOT #11</b>	2023-03-07 18:28
<b>MOT test number</b>	158150757654
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2022-01-14 11:24
<b>MOT test number</b>	817927157393
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Nearside Front Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #9</b>	2021-02-17 08:56
<b>MOT test number</b>	287475488317
<b>Result</b>	✓ Passed

**MOT #8** 2020-09-21 10:17**MOT test number** 312340196427**Result** ✓ Passed**MOT #7** 2019-08-27 13:35**MOT test number** 438989434352**Result** ✓ Passed

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #6** 2018-09-06 16:04**MOT test number** 773831475544**Result** ✓ Passed

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #5** 2018-09-06 15:46**MOT test number** 908708079772**Result** ✗ Failed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn Close To Legal Limit, Inner Shoulder Bald. (5.2.3 (e))

**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**DANGEROUS** Nearside Rear Tyre has ply or cords exposed Inner Shoulder. (5.2.3 (d) (ii))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm 205/50W17X.L. (5.2.3 (e))

**MOT #4** 2017-09-07 10:06**MOT test number** 618076513115**Result** ✓ Passed

- Advice** Item(s) Removed From Drivers View. Prior To Test.
- Advice** Nearside Rear Tyre, Inner Shoulder Bald.
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre, Inner Shoulder Heavily Worn.
- Advice** Nearside Rear Tyre Worn Slightly Out Of Shape.
- Advice** Nearside Rear Tyre worn close to the legal limit 205/50W17X.L. (4.1.E.1)

**MOT #3** 2016-09-07 14:49**MOT test number** 404379129041**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2015-09-07 15:22**MOT test number** 759729466676**Result** ✓ Passed**MOT #1** 2014-09-03 14:58**MOT test number** 145886144223**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
15 March 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	15 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>LR61CGG</b>
Plate since	2019-09-28
Current registration	<b>LR61CGG</b>
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-07
Last registration	2024-03-16
Complete history	<a href="#">See info</a>



Registration #1	2011-09-07	27 mi
Registration #2	2014-09-03	5.464 mi
Registration #3	2015-09-07	10.528 mi
Registration #4	2016-09-07	18.886 mi
Registration #5	2017-09-07	26.242 mi
Registration #6	2018-09-06	36.344 mi
Registration #7	2018-09-06	36.344 mi
Registration #8	2019-09-06	36.344 mi
Registration #9	2019-09-06	36.344 mi
Registration #10	2019-09-06	36.344 mi
Registration #11	2019-09-06	36.344 mi
Registration #12	2019-09-06	36.344 mi
Registration #13	2019-09-06	36.344 mi
Registration #14	2019-09-06	36.344 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1346 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1038586