



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 TDI ALTITUDE
Colour	Black
Year of manufacture	2006
Top speed	125 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	222 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.999 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.3 mpg
Consumption extra urban	32.5 mpg
Consumption combined	25.9 mpg
CO2 emission	287 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-09-17
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



MOT history

MOT expiry date	2024-01-15
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	21
Total items failed	20

MOT #20	2023-01-16 15:06
MOT test number	138843880575
Result	✓ Passed
Next expiry date	2024-01-15
Advice	Rear Sub-frame corroded but not seriously weakened all four suspensions corroded (5.3.3 (b) (ii))

MOT #19	2021-11-27 16:52
MOT test number	991921497515
Result	✓ Passed

MOT #18	2021-11-26 11:12
MOT test number	401513988177
Result	✗ Failed
Fail	Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**MOT #17** 2021-10-05 16:19**MOT test number** 311784917698**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #16** 2020-09-18 14:45**MOT test number** 627116403624**Result** ✓ Passed**MOT #15** 2019-09-20 15:47**MOT test number** 155888025275**Result** ✓ Passed**MOT #14** 2019-09-16 10:58**MOT test number** 449603174262**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))**Fail** Offside Front Brake hose excessively chafed (1.1.12 (b) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13** 2018-09-05 13:37**MOT test number** 137085493758**Result** ✓ Passed**Minor** Nearside Front Brake hose slightly damaged (1.1.12 (b) (i))**MOT #12** 2017-09-09 09:13**MOT test number** 856643846044**Result** ✓ Passed**MOT #11** 2016-08-31 14:15**MOT test number** 275549792150**Result** ✓ Passed**MOT #10** 2016-02-24 16:50**MOT test number** 779314270080**Result** ✓ Passed**MOT #9** 2016-02-17 17:03**MOT test number** 945085516256**Result** ✗ Failed**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Obligatory mirror seriously obscured affecting the rear view (8.1.2a)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #8** 2014-10-28 10:12**MOT test number** 369601704363**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2014-10-28 10:12**MOT test number** 268941804394**Result** ✗ Failed**Pass with rectification** Offside Rear Suspension arm severely distorted (2.4.G.1)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Pass with rectification** Offside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2013-10-19 09:36**MOT test number** 139112693232**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #5** 2012-10-12 10:33**MOT test number** 337896482220**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2011-04-01 17:14
MOT test number	206051091046
Result	✓ Passed
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #3	2011-04-01 11:48
MOT test number	186961991084
Result	✗ Failed
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Fail	Parking brake lever defective so that it cannot be satisfactorily operated (3.1.3c)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Fuel system component leaking (7.2.3)

MOT #2	2010-04-07 11:40
MOT test number	152697290014
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Nail in offside front tyre
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2009-11-14 12:35
MOT test number	621188619358
Result	✗ Failed
Notice	Nail in offside rear tyre
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)



Tax & MOT check

✕  
Untaxed

Tax expired:  
1 September 2022

✕  
MOT

Expired:  
15 January 2024

Tax status	Expired at 1 September
Days left	606 days too late
MOT expiry date	15 January 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YR56VRD
Plate since	2019-06-29
Current registration	 YR56VRD
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-11-03
Last registration	2023-01-16
Complete history	<a href="#">See info</a>



Registration #1	2006-11-03	20 mi
Registration #2	2009-11-14	39.199 mi
Registration #3	2010-04-07	42.830 mi
Registration #4	2011-04-01	51.731 mi
Registration #5	2011-04-01	51.731 mi
Registration #6	2012-10-12	66.957 mi
Registration #7	2013-10-19	77.621 mi
Registration #8	2014-10-28	86.803 mi
Registration #9	2016-02-17	96.545 mi
Registration #10	2016-02-24	96.663 mi
Registration #11	2016-08-31	97.237 mi
Registration #12	2016-09-01	97.237 mi
Registration #13	2016-09-01	97.237 mi
Registration #14	2016-09-01	97.237 mi
Registration #15	2016-09-01	97.237 mi
Registration #16	2016-09-01	97.237 mi
Registration #17	2016-09-01	97.237 mi
Registration #18	2016-09-01	97.237 mi
Registration #19	2016-09-01	97.237 mi
Registration #20	2016-09-01	97.237 mi
Registration #21	2016-09-01	97.237 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2230 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2530 kg
Max. allowed weight	2945 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	BKS 039885