





report date: 2024-03-29

### General information

Make	ABARTH
Model	595 595
Colour	Red
Year of manufacture	2018
Top speed	130 mph
0 - 60 mph	7.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	144 BHP
Max. torque	206 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

### Entry 1

Date 2021-05-24

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

## MOT history

MOT expiry date	2025-04-04
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	17
Total items failed	5

MOT #6	2024-03-23 11:46
MOT test number	658377781604
Result	<b>✓</b> Passed
Next expiry date	2025-04-04

MOT #5	2024-03-23 10:34	
MOT test number	703167207656	
Result	<b>X</b> Failed	
Fail Daytime running lamp not working Both front (4.2.1 (a) (ii))		
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm worn to 1mm (5.2.3 (e))		
Fail Position lamp not working Both front (4.2.1 (a) (ii))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge worn to 2mm (5.2.3 (	(e))	

CarCheck.co.uk page 3/12



Result

SV180KZ

report date: 2024-03-29

✓ Passed

MOT #4 2023-03-27 14:49

**MOT test number** 159895324211

Advice Nearside Front Tyre worn close to legal limit/worn on edge 195 45 16 84V (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 195 45 16 84V (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge 195 45 16 84V (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement LOWER

ARM REAR BUSH (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge 195 45 16 84V (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement LOWER

ARM REAR BUSH (5.3.4 (a) (i))

MOT #3 2022-04-05 10:06

MOT test number 238235759802

Result \rightarrow Passed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/12



report date: 2024-03-29

 MOT #2
 2022-03-14 10:04

 MOT test number
 527158512659

Result X Failed

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Brake pipe likely to become detached or damaged mounting braket (1.1.11 (d) (ii))

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2021-03-16 11:13

MOT test number 459905413707

Result 

Passed

Advice Inner Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))

CarCheck.co.uk page 5/12



SV180KZ report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	4 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



SV180KZ report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this ABARTH? How many owner have? Check it in the premium report and see all owner registrations. Download the full r	
*********	
***************************************	
***********	
********	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this ABARTH had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIK
Plate since	

CarCheck.co.uk page 9/12



SV18OKZ report date: 2024-03-29

Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled.

If not, and you buy this ABARTH then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this ABARTH is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



SV18OKZ report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-03-19
Last registration	2024-03-23
Complete history	See info



Registration #1	2018-03-19	23 mi
Registration #2	2021-03-16	10.919 mi
Registration #3		11.777 es
Registration #4	2022-03-14	16.185 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

# Dimensions & weight

Width	1627 mm
Height	1485 mm
Length	3660 mm
Wheel base	2300 mm
Kerb weight	1035 kg
Max. allowed weight	1425 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	2368389

CarCheck.co.uk page 12/12