



RENAULT



report date: 2024-03-29

General information

| | |
|---------------------|--------------------|
| Make | RENAULT |
| Model | CLIO DYNAMIQUE 16V |
| Colour | Silver |
| Year of manufacture | 2007 |
| Top speed | 114 mph |
| 0 - 60 mph | 11.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 98 BHP |
| Max. torque | 127 Nm at 4.250 rpm |
| Engine capacity | 1.390 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 32.5 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 42.8 mpg |
| CO2 emission | 158 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-04 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-05-11 |
| MOT pass rate | 88 % |
| MOT passed | 14 |
| Failed MOT tests | 2 |
| Total advice items | 10 |
| Total items failed | 2 |

| | |
|------------------|------------------|
| MOT #16 | 2024-04-12 11:50 |
| MOT test number | 890733210898 |
| Result | ✓ Passed |
| Next expiry date | 2025-05-11 |

| | |
|-----------------|------------------|
| MOT #15 | 2023-04-21 08:21 |
| MOT test number | 948469017031 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #14 | 2022-05-05 11:27 |
| MOT test number | 933100619055 |
| Result | ✓ Passed |

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2022-05-05 08:40**MOT test number** 429109906251**Result** ✗ Failed**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Hydraulic brake cylinder leaking hydraulic fluid (1.1.16 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2021-05-12 12:05**MOT test number** 720179386997**Result** ✓ Passed**MOT #11** 2021-05-12 11:31**MOT test number** 375048272299**Result** ✗ Failed**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #10** 2020-01-14 10:24**MOT test number** 901766789867**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #9** 2019-01-10 11:11**MOT test number** 712338041384**Result** ✓ Passed



| | |
|---------------|------------------|
| MOT #8 | 2018-01-09 10:12 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 303804658508 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #7 | 2017-01-12 12:17 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 726605343749 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #6 | 2016-01-12 09:29 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 163764811618 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #5 | 2015-01-13 11:00 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 287473215096 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #4 | 2014-01-08 11:32 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 126868604081 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #3 | 2013-01-10 12:27 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 796630513075 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|--|
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |
|---------------|--|

| | |
|---------------|------------------|
| MOT #2 | 2012-01-23 09:25 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 148753822079 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



| | |
|-----------------|------------------|
| MOT #1 | 2010-11-09 10:44 |
| MOT test number | 440603210361 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
11 May 2025

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 366 |
| MOT expiry date | 11 May 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | | |
|-------------------|---------|------|
| Finance company | RENAULT | 2024 |
| Date of agreement | RENAULT | 2024 |
| Agreement type | RENAULT | 2024 |
| Agreement term | RENAULT | 2024 |
| Agreement number | RENAULT | 2024 |
| Contact info | RENAULT | 2024 |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2007-11-13 |
| Last registration | 2024-04-12 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-11-13 | 27 mi |
| Registration #2 | 2010-11-09 | 11.707 mi |
| Registration #3 | 2012-01-23 | 14.729 mi |
| Registration #4 | 2013-01-10 | 17.141 mi |
| Registration #5 | 2014-01-08 | 19.500 mi |
| Registration #6 | 2015-01-13 | 22.088 mi |
| Registration #7 | 2016-01-12 | 24.361 mi |
| Registration #8 | 2017-01-12 | 26.889 mi |
| Registration #9 | 2018-01-09 | 30.185 mi |
| Registration #10 | 2019-01-09 | 33.577 mi |
| Registration #11 | 2020-01-09 | 36.969 mi |
| Registration #12 | 2021-01-09 | 40.361 mi |
| Registration #13 | 2022-01-09 | 43.753 mi |
| Registration #14 | 2023-01-09 | 47.145 mi |
| Registration #15 | 2024-01-09 | 50.537 mi |
| Registration #16 | 2025-01-09 | 53.929 mi |
| Registration #17 | 2026-01-09 | 57.321 mi |
| Registration #18 | 2027-01-09 | 60.713 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1940 mm |
| Height | 1496 mm |
| Length | 3986 mm |
| Wheel base | 2575 mm |
| Kerb weight | 1135 kg |
| Max. allowed weight | 1625 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 5 |

| | |
|---------------|---------|
| Engine number | D078306 |
|---------------|---------|