



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Grey
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-03-12
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #13</b>	2022-03-22 16:25
<b>MOT test number</b>	884182897807
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-03-21
<b>Advice</b>	Nearside Rear Nail in tyre
<b>Minor</b>	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

<b>MOT #12</b>	2021-07-15 09:53
<b>MOT test number</b>	161861284434
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Front Exhaust mounting defective (6.1.2 (a))

<b>MOT #11</b>	2021-07-15 09:53
<b>MOT test number</b>	268766012918
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Front Exhaust mounting defective (6.1.2 (a))
<b>Minor</b>	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Pass with rectification</b>	Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #10** 2020-07-17 16:09**MOT test number** 192803594393**Result** ✓ Passed**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #9** 2019-05-16 07:34**MOT test number** 666221212592**Result** ✓ Passed**Advice** Both front tyre treads getting low**MOT #8** 2018-05-09 11:54**MOT test number** 225782234946**Result** ✓ Passed**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**MOT #7** 2018-05-09 11:54**MOT test number** 892147747126**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**MOT #6** 2017-04-13 08:29**MOT test number** 894200641440**Result** ✓ Passed

**MOT #5** 2016-05-20 11:55**MOT test number** 648271024060**Result** ✓ Passed

**Advice** Offside Front Front suspension has slight movement at a wishbone pin or bush rear bush (2.5.A.1c)

**Advice** Oil leak

**Advice** Nearside Front Front suspension has slight movement at a wishbone pin or bush rear bush (2.5.A.1c)

**MOT #4** 2016-05-20 11:17**MOT test number** 996523550460**Result** ✗ Failed

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 185/65/15 (4.1.E.1)

**Advice** Nearside Front Front suspension has slight movement at a wishbone pin or bush rear bush (2.5.A.1c)

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Advice** Oil leak

**Advice** Offside Front Front suspension has slight movement at a wishbone pin or bush rear bush (2.5.A.1c)

**MOT #3** 2015-05-19 10:18**MOT test number** 209639335176**Result** ✓ Passed**MOT #2** 2014-05-13 10:09**MOT test number** 268313134162**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Both rear tyres perished 0210 DOT CODES

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2013-05-21 09:49
MOT test number	769491243166
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>HN10KHL</b>
Plate since	2019-03-29
Current registration	<b>HN10KHL</b>
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-05-26
Last registration	2022-03-22
Complete history	<a href="#">See info</a>



Registration #1	2010-05-26	9 mi
Registration #2	2013-05-21	25.850 mi
Registration #3	2014-05-13	34.533 mi
Registration #4	2015-05-19	43.483 mi
Registration #5	2016-05-20	52.241 mi
Registration #6	2016-05-20	52.241 mi
Registration #7	2017-04-13	59.390 mi
Registration #8	2018-05-09	62.281 mi
Registration #9	2019-05-09	65.277 mi
Registration #10	2019-05-09	65.277 mi
Registration #11	2019-05-09	65.277 mi
Registration #12	2019-05-09	65.277 mi
Registration #13	2019-05-09	65.277 mi
Registration #14	2019-05-09	65.277 mi
Registration #15	2019-05-09	65.277 mi

More info >



Safety ratings

NCAP rating 

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX7U3431903