



YJ090GX

report date: 2024-03-29

General information

Make	KIA
Model	SEDONA
Colour	Blue
Year of manufacture	2009
Gearbox	-

Engine & fuel consumption

Engine capacity	2.902 cc
Fuel type	Diesel
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-22
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	15
Total items failed	11

MOT #17	2024-02-21 10:27
MOT test number	984673064854
Result	✓ Passed
Next expiry date	2025-02-22

MOT #16	2023-02-10 10:17
MOT test number	199350586901
Result	✓ Passed

MOT #15	2022-02-15 15:10
MOT test number	193130240993
Result	✓ Passed

MOT #14	2021-02-23 13:17
MOT test number	537570768019
Result	✓ Passed
Advice	Coolant leak x 2

**MOT #13** 2021-02-23 11:10**MOT test number** 882133957518**Result** ✗ Failed**Advice** Coolant leak x 2**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Brake lever has restricted free movement (1.1.15 (e))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #12** 2019-08-30 13:09**MOT test number** 539014832700**Result** ✓ Passed**MOT #11** 2018-09-20 14:21**MOT test number** 542661673893**Result** ✓ Passed**MOT #10** 2017-09-07 14:42**MOT test number** 911085899400**Result** ✓ Passed**MOT #9** 2017-09-07 09:38**MOT test number** 548829067788**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #8** 2016-09-26 10:45**MOT test number** 959191934206**Result** ✓ Passed**MOT #7** 2016-09-21 14:00**MOT test number** 485869298061**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Power steering component(s) leaking from a failed seal (2.3.3b)**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**MOT #6** 2015-06-18 09:24**MOT test number** 965219565152**Result** ✓ Passed**MOT #5** 2014-06-30 13:26**MOT test number** 877021584127**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**MOT #4** 2014-06-30 13:26**MOT test number** 266891084152**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #3 2013-07-20 11:07

MOT test number 387951903298

Result ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Power steering component(s) has slight seepage from a component (2.3.3b)
- Notice** Items removed from driver's view prior to test
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2013-07-20 11:07

MOT test number 637951303247

Result ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Items removed from driver's view prior to test
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Power steering component(s) has slight seepage from a component (2.3.3b)

MOT #1 2012-07-19 15:26

MOT test number 769231102287

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
22 February 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	YJ09OGX
Plate since	2024-03-29
Current registration	YJ09OGX
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-08-04
Last registration	2024-02-21
Complete history	See info



Registration #1	2009-08-04	17 mi
Registration #2	2012-07-19	41.520 mi
Registration #3	2013-07-20	58.214 mi
Registration #4	2014-06-30	67.833 mi
Registration #5	2015-06-18	70.921 mi
Registration #6	2016-09-21	74.785 mi
Registration #7	2016-09-26	74.843 mi
Registration #8	2017-09-07	76.128 mi
Registration #9	2017-09-07	76.128 mi
Registration #10	2018-09-07	76.128 mi
Registration #11	2018-09-07	76.128 mi
Registration #12	2018-09-07	76.128 mi
Registration #13	2018-09-07	76.128 mi
Registration #14	2018-09-07	76.128 mi
Registration #15	2018-09-07	76.128 mi
Registration #16	2018-09-07	76.128 mi
Registration #17	2018-09-07	76.128 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Number of seats 7

Engine number J3