



YKIIPZZ

report date: 2024-03-28

General information

Make	MAZDA
Model	CX-7 D SPORT TECH
Colour	Silver
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.184 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-02-11
Pictures	36
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-01-25
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	31
Total items failed	2

MOT #12 2022-01-26 14:18

MOT test number 361274851500

Result ✓ Passed

Next expiry date 2023-01-25

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

Advice Rear Tyre slightly damaged/cracking or perishing both rear tyres perished (5.2.3 (d) (ii))

MOT #11 2021-03-01 16:37

MOT test number 911061332882

Result ✓ Passed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm main bush. (5.3.4 (a) (i))

Advice Nearside Rear Nail in tyre

Advice Rear brakes rust.

Advice Both rear tyres perishing.

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm main bush. (5.3.4 (a) (i))

Advice Diesel particulate filter light on dash flashing.

Advice Underside rust.

**MOT #10**

2021-02-26 09:55

MOT test number

596538341477

Result**✗ Failed****Advice** Rear brakes rust.**Advice** Both rear tyres perishing.**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm main bush. (5.3.4 (a) (i))**Advice** Diesel particulate filter light on dash flashing.**Advice** Nearside Rear Nail in tyre**Advice** Underside rust.**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm main bush. (5.3.4 (a) (i))**MOT #9**

2020-02-10 15:27

MOT test number

497873613305

Result**✓ Passed****Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush (5.3.4 (a) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush (5.3.4 (a) (i))

**MOT #8**

2020-02-10 10:31

MOT test number

899927975386

Result

✗ Failed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush (5.3.4 (a) (i))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush (5.3.4 (a) (i))

Advice Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7

2019-02-18 09:19

MOT test number

347315838718

Result

✓ Passed

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

MOT #6

2018-02-09 09:21

MOT test number

802641258334

Result

✓ Passed

MOT #5

2017-02-16 09:47

MOT test number

828785585310

Result

✓ Passed

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #4

2016-03-07 11:25

MOT test number

891318059732

Result

✓ Passed



MOT #3	2015-03-09 16:27
MOT test number	165678365076
Result	✓ Passed

MOT #2	2015-03-09 14:07
MOT test number	387098065042
Result	✗ Failed
Fail	Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
Fail	Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)

MOT #1	2014-02-13 15:43
MOT test number	195904144041
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✕
Untaxed

Tax expired:
15 April 2024

✕
MOT

Expired:
25 January 2023

Tax status	Expired at 15 April 2024
Days left	13 days too late
MOT expiry date	25 January 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	YK11PZZ
Plate since	2019-03-28
Current registration	YK11PZZ
Plate since	2019-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-08
Last registration	2022-01-26
Complete history	See info



Registration #1	2011-03-08	6 mi
Registration #2	2014-02-13	37.495 mi
Registration #3	2015-03-09	46.485 mi
Registration #4	2015-03-09	46.485 mi
Registration #5	2016-03-07	54.988 mi
Registration #6	2017-02-16	62.032 mi
Registration #7	2018-02-09	76.484 mi
Registration #8	2019-01-29	85.277 mi
Registration #9	2019-01-29	85.277 mi
Registration #10	2019-01-29	85.277 mi
Registration #11	2019-01-29	85.277 mi
Registration #12	2019-01-29	85.277 mi
Registration #13	2019-01-29	85.277 mi
Registration #14	2019-01-29	85.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	76%
Children	79%
Pedestrian	43%
Safety systems	71%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4700 mm
Wheel base	2750 mm
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R210287355