



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Silver
Year of manufacture	2010
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 2


Date	2023-03-24
Pictures	9
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-07-17
Pictures	33
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-20
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	21
Total items failed	0

MOT #14	2024-03-18 12:57
MOT test number	387305714493
Result	✓ Passed
Next expiry date	2025-03-20
Advice	Rear Child Seat fitted not allowing full inspection of adult belt

MOT #13	2024-03-18 11:35
MOT test number	680092151921
Result	✗ Failed
Advice	Rear Child Seat fitted not allowing full inspection of adult belt
MAJOR	Nearside Rear Service brake excessively binding (1.2.1 (f))
MAJOR	Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
MAJOR	Offside Rear Service brake grabbing severely (1.2.1 (c))

MOT #12	2023-03-21 13:01
MOT test number	923741677833
Result	✓ Passed

**MOT #11** 2022-07-27 16:54**MOT test number** 301750128467**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**MOT #10** 2021-12-30 17:46**MOT test number** 548217779073**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt 3 child seats in vehicle.**Advice** Nearside Front Shock absorbers has a slightly worn bush Slight play in top mount. (5.3.2 (c))**MOT #9** 2021-12-30 11:39**MOT test number** 743147096078**Result** ✗ Failed**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2020-09-02 14:54**MOT test number** 180908054335**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2019-03-16 10:59**MOT test number** 417080134925**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt Rear Drivers Seat**Advice** Child Seat fitted not allowing full inspection of adult belt Rear Passenger Seat**Advice** Child Seat fitted not allowing full inspection of adult belt Rear Centre Seat**MOT #6** 2018-03-07 14:59**MOT test number** 209464463310**Result** ✓ Passed**Advice** All four tyres perishing**MOT #5** 2017-03-17 15:32**MOT test number** 794549695664**Result** ✓ Passed**MOT #4** 2016-03-09 14:12**MOT test number** 787722899582**Result** ✓ Passed**MOT #3** 2015-03-11 14:41**MOT test number** 498780375045**Result** ✓ Passed**MOT #2** 2014-03-12 14:09**MOT test number** 396401274015**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #1	2013-03-13 15:42
MOT test number	508792373048
Result	✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)
Notice	Vehicle's internal headlight adjuster altered to recheck lights



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
20 March 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-28
Previous owner since	2019-09-28
Number of owners	1
Current owner since	2019-09-28
Previous owner since	2019-09-28

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 BV100CN
Plate since	2019-09-28
Current registration	 BV100CN
Plate since	2019-09-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-31
Last registration	2024-03-18
Complete history	See info



Registration #1	2010-03-31	15 mi
Registration #2	2013-03-13	8.167 mi
Registration #3	2014-03-12	10.540 mi
Registration #4	2015-03-11	12.598 mi
Registration #5	2016-03-09	15.033 mi
Registration #6	2017-03-17	16.509 mi
Registration #7	2018-03-07	17.270 mi
Registration #8	2019-03-16	22.586 mi
Registration #9	2020-09-02	35.151 mi
Registration #10	2021-03-20	35.377 mi
Registration #11	2022-03-20	35.377 mi
Registration #12	2023-03-20	35.377 mi
Registration #13	2024-03-20	35.377 mi
Registration #14	2025-03-20	35.377 mi
Registration #15	2026-03-20	35.377 mi
Registration #16	2027-03-20	35.377 mi
Registration #17	2028-03-20	35.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1226589